

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA
Dirección AFTN: LEANZXTA
Teléfono: +34 913 213 363
E-mail: ais@enaire.es
Web: www.enaire.es

ENAIRE
DIVISIÓN DE INFORMACIÓN AERONÁUTICA
Avda. Aragón, 330. EDIFICIO 2
P.E. Las Mercedes - 28022 MADRID

SUP 97/22

14-JUL-22

AD

SUP 97/22

14JUL22/14JUL23EST

NOTA: SUP EST, sólo se cancelará por NOTAM, SUP o enmienda al AIP.

ALMERÍA AD (LEAM).- Luces de aproximación degradadas y 4 luces del lado izquierdo de la RWY 25 inutilizables.

Hasta el 14 de julio 2023 estimado, el sistema de luces de aproximación de la RWY 25 estará degradado en un 29 por ciento y 4 luces consecutivas del lado izquierdo del eje de la RWY 25 situadas a 450 metros desde el umbral estarán inutilizables.

SUP 97/22

14JUL22/14JUL23EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

ALMERÍA AD (LEAM).- Approach lighting degraded and 4 lights on the left side of RWY 25 unserviceable.

Until 14 July 2023 (estimated), the RWY 25 approach lighting system is degraded by 29 per cent, and 4 consecutive lights on the left side of the RWY 25 centre line situated 450 metres from the threshold are unserviceable.

INTENCIONADAMENTE EN BLANCO
INTENTIONALLY BLANK