

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA

Dirección AFTN: LEANZXTA

Teléfono: +34 913 213 363

E-mail: ais@enaire.es

Web: www.enaire.es

ENAI
DIVISIÓN DE INFORMACIÓN AERONÁUTICA
c/ Campezo, 1. EDIFICIO 2
Kudos Innovation Campus Las Mercedes
28022 Madrid (ESPAÑA)

SUP 07/26

22-JAN-26

AD

CANCEL: SUP 175/25

SUP 07/26

22JAN26/22JAN27EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

PALMA DE MALLORCA AD (LEPA/LESJ).- Scheduled withdrawal of DVOR/DME POS of Pollensa.

Until 22 January 2027 (estimated), actions related to the replacement of DVOR/DME POS will be carried out, and the system will be out of service.

Affected procedure / segment:

Palma de Mallorca airport:

- STAR 3 RWY 24L/24R:

LORES1P radar assistance.

TOLSO2P radar assistance segment between LISAS-POS.

The following procedures / segments will be unavailable (U/S), although the “connecting points” of the SIDs and STARs are still plannable:

- SID 1 RWY 06L: DRAGO4L, EPAMA3L, GALAT4L.

- SID 2 RWY 06R: DRAGO5B, EPAMA4B, GALAT5B.

- STAR 1 RWY 06L/06R: LORES4M.

- STAR 3 RWY 24L/24R: holding over DVOR/DME POS and holding over POSBA.

- IAC 11 ILS Z RWY 24L: initial segment and holding over DVOR/DME POS.

- IAC 12 ILS Y RWY 24L initial segment and holding over DVOR/DME POS.

- IAC 13 LOC RWY 24L: initial segment and holding over DVOR/DME POS.

- IAC 16 ILS Z RWY 24R: initial segment and holding over DVOR/DME POS.

- IAC 17 ILS Y RWY 24R: initial segment and holding over DVOR/DME POS.
- IAC 18 ILS X RWY 24R: initial segment and holding over DVOR/DME POS.
- IAC 19 VOR RWY 24R: initial segment and holding over DVOR/DME POS.

The remaining procedures will be operational.

- SUP 07/26 -