

AD 2-LEAB DEP 1.

## INSTRUMENT DEPARTURES (DEP)

### RUNWAY 09

#### ASTRO TWO WHISKEY DEPARTURE (ASTRO2W)

Climb on runway heading until 4000 ft or above. Turn left to follow R-080 TAB, direct to cross ASTRO at FL100 or above.

Minimum climb gradient of 5.0% up to ASTRO.

#### BAILEN TWO WHISKEY DEPARTURE (BLN2W)

Climb on runway heading until 4000 ft or above. Turn right to magnetic heading 272° to follow R-241 TAB, direct to cross VOR/DME BLN at FL100 or above.

#### MOTIL TWO WHISKEY DEPARTURE (MOTIL2W)

Climb on runway heading until 4000 ft or above. Turn left to magnetic heading 346° to follow R-009 TAB, direct to cross MOTIL at FL100 or above.

#### YESTE TWO WHISKEY DEPARTURE (YES2W)

Climb on runway heading until 4000 ft or above. Turn right to magnetic heading 245° to follow R-213 TAB, direct to cross VOR/DME YES at FL100 or above.

### RUNWAY 27

#### ASTRO TWO X-RAY DEPARTURE (ASTRO2X)

Climb on runway heading until 4000 ft or above. Turn right to magnetic heading 110° to follow R-080 TAB, direct to cross ASTRO at FL100 or above.

#### BAILEN TWO X-RAY DEPARTURE (BLN2X)

Climb on runway heading until 4000 ft or above. Turn left to magnetic heading 212° to follow R-241 TAB, direct to cross VOR/DME BLN at FL100 or above.

#### MOTIL TWO X-RAY DEPARTURE (MOTIL2X)

Climb on runway heading until 4000 ft or above. Turn right to magnetic heading 046° to follow R-009 TAB, direct to cross MOTIL at FL100 or above.

#### YESTE TWO X-RAY DEPARTURE (YES2X)

Climb on runway heading until 4000 ft or above. Turn left to magnetic heading 185° to follow R-213 TAB, direct to cross DVOR/DME YES at FL100 or above.