


ALCOL2Y HIJ2Z MGA2V
MGA2Z ONUBA2X PIMOS2Y
PIMOS2Z



INSTRUMENT DEPARTURES (DEP)

NOTE APPLICABLE TO ALL DEP:

- INITIAL CLEARANCE: FL080.

INITIAL CLEARANCE: FL080.

RUNWAY 28

ALCOL TWO YANKEE DEPARTURE (ALCOL2Y)

Climb on runway heading to reach 2000 ft. Turn left to follow R-094 AOG to intercept and follow R-197 MRN direct to VOR/DME MRN. Turn right to follow R-053 MRN direct to cross ALCOL at FL080 or above.

HINOJOSA TWO ZULU DEPARTURE (HIJ2Z)

Climb on runway heading to reach 2000 ft. Turn right to follow R-345 AOG direct to ALAOS. Turn right to follow R-223 HIJ direct to ROCIO. Direct to ARROS. Direct to VOR/DME HIJ.

MÁLAGA TWO VICTOR DEPARTURE (MGA2V)

Climb on runway heading to reach 2000 ft. Turn left to follow R-327 VJF direct to DVOR/DME VJF. Turn left to follow R-067 VJF direct to TOBOS, direct to DVOR/DME MGA.

MÁLAGA TWO ZULU DEPARTURE (MGA2Z)

Climb on runway heading to reach 2000 ft. Turn left to follow R-094 AOG direct to TOBOS. Turn left to follow R-247 MGA, direct to DVOR/DME MGA.

ONUBA TWO X-RAY DEPARTURE (ONUBA2X)

Climb on runway heading to reach 2000 ft. Turn right to follow R-345 AOG direct to ALAOS. Turn left to follow magnetic heading 283° direct to ONUBA.

PIMOS TWO YANKEE DEPARTURE (PIMOS2Y)

Climb on runway heading to reach 2000 ft. Turn left to follow R-094 AOG direct to TOBOS. Turn right to follow R-145 SVL direct to MABEL. Turn right to follow magnetic heading 254° direct to PIMOS.

PIMOS TWO ZULU DEPARTURE (PIMOS2Z)

Climb on runway heading to reach 2000 ft. Turn left to follow R-327 VJF direct to DVOR/DME VJF. Turn left to follow R-067 VJF direct to TOBOS. Turn right to follow R-145 SVL direct to MABEL. Turn right to follow magnetic heading 254° direct to PIMOS.