

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA

Dirección AFTN: LEANZXTA

Teléfono: +34 913 213 363

E-mail: ais@enaire.es

Web: www.enaire.es

ENAI
DIVISIÓN DE INFORMACIÓN AERONÁUTICA
c/ Campezo, 1. EDIFICIO 2
Kudos Innovation Campus Las Mercedes
28022 Madrid (ESPAÑA)

SUP 137/25

07-AUG-25

AD

SUP 137/25

07AUG25/07AUG26EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

SAN SEBASTIÁN AD (LESO).- Scheduled withdrawal of DVOR/DME BTZ.

Until 07 August 2026 (estimated), the DVOR/DME BTZ shall be out of service due to system replacement (see NOTAM LFBZ F0359/25).

The instrumental manoeuvres affected by the scheduled unavailability of the DVOR/DME BTZ are set out below:

- LESO SID 1 RWY 04 BTZ1B, BLV4B, CEGAM3D, PPN1B: procedures not usable.
- LESO SID 2 RWY 04 BTZ1Z, BLV2Z, CEGAM2Z, PPN1Z: procedures not usable.
- LESO SID 4 RWY 22 BTZ2A: procedures not usable.
- LESO SID 5 RWY 22 BTZ1Y: procedures not usable.
- LESO IAC 1 VOR RWY 22: initial segment, of the approaches, from IAF BTZ and IAF OSGOT not usable.

- SUP 137/25 -

