

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA

Dirección AFTN: LEANZXTA

Teléfono: +34 913 213 363

E-mail: ais@enaire.es

Web: www.enaire.es

ENAIRE

DIVISIÓN DE INFORMACIÓN AERONÁUTICA

c/ Campezo, 1. EDIFICIO 2

Kudos Innovation Campus Las Mercedes

28022 Madrid (ESPAÑA)

SUP 192/26

AIRAC 17-SEP-26

EFFECTIVE DATE WEF 29-OCT-26

ENR/AD

SUP 192/26

02NOV26/02NOV27EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

PALMA DE MALLORCA AD (LEPA/LESJ).- Temporary unavailability of DVOR/DME Capdepera (CDP).

DVOR/DME Capdepera (CDP) Unavailability

From 02 November 2026 until 02 November 2027 (estimated), the DVOR/DME Capdepera (CDP) will be unavailable due to system replacement.

Works involving machinery and personnel will be carried out at and in the vicinity of the DVOR/DME CDP site in order to decommission the current system and install the new one.

Any additional operational incidents will be notified by NOTAM.

Operational Impact During DVOR/DME CDP Unavailability

ENR 3.2

- DVOR/DME CDP not available as a reference station for the airways described in ENR 3.2.

Palma de Mallorca Airport (LEPA/LESJ)

SID 1 RWY 06L

- Departure CDP2L: R-090 JOA / 8.5 DME JOA - DVOR/DME CDP segment affected. Contingency departure available.

SID 2 RWY 06R

- Departure CDP2E: R-090 JOA / 8.5 DME JOA - DVOR/DME CDP segment affected.

Contingency departure available.

SID 4 RWY 24L

- Departure BAVR3Z: BAVR definition affected. Same SID available using MJV radials.
- Departure BAVR5A: BAVR definition affected. Same SID available using MJV radials.

STAR 1 RWY 06L/06R

- Arrival KENAS4M: All legs affected.
- Arrival LUNIK4M: All legs affected.
- Arrival RIXOT3M: All legs affected.
- Arrival TOLSO4M: INPUS definition affected.

Radar assistance available.

STAR 3 RWY 24L/24R

- Arrival KENAS3P: All legs affected.
- Arrival LUNIK3P: All legs affected.
- Arrival MAMEB2P: All legs affected.
- Arrival MORSS3P: DVOR/DME MHN - DVOR/DME CDP (IAF) segment and holding affected.
- Arrival RIXOT2P: All legs affected.

Radar assistance available.

IAC Approaches

- IAC/3.1 ILS Z RWY 06L: Procedure not available.
- IAC/4.1 ILS Y RWY 06L: Procedure not available.
- IAC/5.1 VOR RWY 06L: Procedure not available.
- IAC/11.1 ILS Z RWY 24L: Initial segment and holding over DVOR/DME CDP not available.
- IAC/12.1 ILS Y RWY 24L: Procedure not available.
- IAC/13.1 LOC RWY 24L: Initial segment and holding over DVOR/DME CDP not available.
- IAC/16.1 ILS Z RWY 24R: Initial segment and holding over DVOR/DME CDP not available.
- IAC/17.1 ILS Y RWY 24R: Procedure not available.

- IAC/18.1 ILS X RWY 24R: Initial segment and holding over DVOR/DME CDP not available.
- IAC/19.1 VOR RWY 24R: Initial segment and holding over DVOR/DME CDP not available.

Menorca Airport (LEHM)

STAR 1 RWY 01

- Arrival CDP2B: Initial point of arrival affected.

Radar assistance available.

STAR 2 RWY 19

- Arrival CDP2F: Initial point of arrival affected.

Radar assistance available.