

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA

Dirección AFTN: LEANZXTA

Teléfono: +34 913 213 363

E-mail: ais@enaire.es

Web: www.enaire.es

ENAIRE
DIVISIÓN DE INFORMACIÓN AERONÁUTICA
c/ Campezo, 1. EDIFICIO 2
Kudos Innovation Campus Las Mercedes
28022 Madrid (ESPAÑA)

SUP 50/25

20-MAR-25

AD

CANCEL: SUP 73/24

SUP 50/25

20MAR25/20MAR26EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

CIUDAD REAL AD (LERL).- Closure of TWY E2 and TWYT between Gate B and TWY E3.

Until 20 March 2026 (estimated), TWY E2 and TWYT between Gate B and TWY E3 will be closed.

As a consequence, the arrival and departure procedures of RWY 10/28 will be modified as follows:

- Arrivals to RWY 10:

TWY E2 not available. Aircraft must taxi to the turn pad and backtrak (daytime only). No aircraft may be waiting in TWY E1.

- Departures via RWY 10:

No aircraft may be waiting in TWY E1 in cases of abandoned take-off which must return to the aircraft stand.

- Arrivals to RWY 28:

These shall be conducted as normal, except that no aircraft may be waiting in TWY E1.

- Departures via RWY 28:

Aircraft must enter the runway via TWY E1, continue along the runway to the runway turn pad, backtrack and line up for departure (daytime only).

No aircraft may be waiting in TWY E1 in cases of abandoned take-off which must return to the aircraft stand.

- SUP 50/25 -