



CAMBIOS: LED97A. //
CHANGES: LED97A.

MURCIA / San Javier AD

SALIDAS POR INSTRUMENTOS (DEP)

RWY 05R

SALIDA SAN JAVIER UNO ALFA (VSJ1A)

Subir en rumbo de pista hasta 5.0 DME VSJ, virar a la derecha para seguir R-156 VSJ. Virar a la derecha para seguir arco 15.0 DME VSJ para seguir R-196 VSJ a FL120 o superior.

Proceder a VOR/TAC VSJ a nivel de vuelo asignado.

RWY 23L

SALIDA SAN JAVIER UNO BRAVO (VSJ1B)

Subir en rumbo de pista hasta 5.0 DME VSJ, virar a la izquierda para seguir R-156 VSJ, cruzando el R-196 VSJ a FL100 o inferior, virar a la derecha para seguir arco 15.0 DME VSJ para seguir R-196 VSJ a FL120 o superior.

Proceder a VOR/TAC VSJ a nivel de vuelo asignado.

INSTRUMENT DEPARTURES (DEP)

RWY 05R

SAN JAVIER ONE ALPHA DEPARTURE (VSJ1A)

Climb on runway heading up to 5.0 DME VSJ, turn right to follow R-156 VSJ. Turn right to follow 15.0 DME VSJ arc to follow R-196 VSJ at FL120 or above.

Proceed to VOR/TAC VSJ at flight level assigned.

RWY 23L

SAN JAVIER ONE BRAVO DEPARTURE (VSJ1B)

Climb on runway heading up to 5.0 DME VSJ, turn left to follow R-156 VSJ, crossing R-196 VSJ at FL100 or below, turn right to follow 15.0 DME VSJ arc to follow R-196 VSJ at FL120 or above.

Proceed to VOR/TAC VSJ at flight level assigned.