

LIST OF HAND AMENDMENTS TO THE AIP

ENR

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
SEVERAL CHARTS	<p>Obstacles of more than 100 m not up-to-date on several charts. Indicated on the AIP website with a warning sign (!).</p> <p>You can look up the correct value in Insignia (https://insignia.enaire.es/) either in the interactive map, with this layer activated, or in the enroute navigation charts in PDF (https://aip.enaire.es/AIP/CartasInsignialImpresas-es.html).</p> <p>The link for the enroute navigation charts in English PDF is: https://aip.enaire.es/AIP/CartasInsignialImpresas-en.html</p>	AMDT 353/22

AD

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
AD 2 – AD 3 SEVERAL AD	<p>AMA values not up-to-date on several charts. Indicated on the AIP website with a warning sign (!).</p> <p>You can look up the correct value in Insignia (https://insignia.enaire.es/) either in the interactive map, with this layer activated, or in the enroute navigation charts in PDF (https://aip.enaire.es/AIP/CartasInsignialmpresas-es.html).</p> <p>The link for the enroute navigation charts in English PDF is: https://aip.enaire.es/AIP/CartasInsignialmpresas-en.html</p>	
	<p>Restricted aerodromes not up-to-date on several charts. Indicated on the AIP website with a warning sign (!).</p> <p>You can look up the correct value in Insignia (https://insignia.enaire.es/) either in the interactive map, with this layer activated, or in the enroute navigation charts in PDF (https://aip.enaire.es/AIP/CartasInsignialmpresas-es.html).</p> <p>The link for the enroute navigation charts in English PDF is: https://aip.enaire.es/AIP/CartasInsignialmpresas-en.html</p>	
	<p>Sport activities not up-to-date on several charts. Indicated on the AIP website with a warning sign (!).</p> <p>You can look up the correct value in Insignia (https://insignia.enaire.es/) either in the interactive map, with this layer activated, or in the enroute navigation charts in PDF (https://aip.enaire.es/AIP/CartasInsignialmpresas-es.html).</p> <p>The link for the enroute navigation charts in English PDF is: https://aip.enaire.es/AIP/CartasInsignialmpresas-en.html</p>	
	<p>Obstacles of more than 100 m not up-to-date on several charts. Indicated on the AIP website with a warning sign (!).</p> <p>You can look up the correct value in Insignia (https://insignia.enaire.es/) either in the interactive map, with this layer activated, or in the enroute navigation charts in PDF (https://aip.enaire.es/AIP/CartasInsignialmpresas-es.html).</p> <p>The link for the enroute navigation charts in English PDF is: https://aip.enaire.es/AIP/CartasInsignialmpresas-en.html</p>	

ALBACETE

AD 2-LEAB

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
VAC 1.1 / 15-JUN-23 VAC 2.1 / 15-JUN-23	Replace the published airway information with: M985-FL095.	AMDT 378/24

ANDORRA-LA SEU DURGELL

AD 2-LESU

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
VAC 1.1 / 25-JAN-24	Delete information regarding airways.	AMDT 378/24

[Redacted content]		
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]

CÁDIZ/Rota

AD 2-LERT

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
VAC 1.1 / 13-JUL-23	Replace the published airway information with: N857-FL095.	AMDT 378/24

LANZAROTE/César Manrique Lanzarote

AD 2-GCRR

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED AMENDMENT BY
IAC/2.3 / 02-DEC-21 IAC/3.3 / 02-DEC-21 IAC/5.1 / 02-DEC-21 IAC/6.1 / 02-DEC-21	The coordinates of the following nav aids: DVOR LTE, LZR, should be replaced by those of their corresponding DME.	AMDT 378/24

[Redacted content]		
[Redacted content]	[Redacted content]	[Redacted content]
[Redacted content]	[Redacted content]	[Redacted content]

TERUEL

AD 2-LETL

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
VAC 1.1 / 22-FEB-24	Replace the published airway information with: M176-FL095.	AMDT 378/24

ALGECIRAS

AD 3-LEAG

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
VAC 1.1 / 28-DEC-23	Replace the published airway information with: M985-FL095.	AMDT 378/24

LOGROÑO/Agoncillo

AD 3-LELO

PAGES AFFECTED	AMENDMENT TEXT	INTRODUCED BY AMENDMENT
VAC 1.1 / 14-JUL-22	The correct lateral limits of CTR LOGROÑO are the ones included in AD 3-LELO 3 item16. CTA LOGROÑO (Área 1) modify and include CTA LOGROÑO (Área 2) according to ENR 2.1-16.	AMDT 366/23
VAC 1.1 / 14-JUL-22	Replace the published airway information with: T430-FL105, L866-FL065, Q210-FL075, T429-FL085, M299-FL065.	AMDT 378/24