





CAMBIOS: DECLINACIÓN MAGNÉTICA, RUMBOS, RADIALES, DESIGNADOR MANIOBRA.

CHANGES: MAGNETIC VARIATION, HEADINGS, RADIALS, MANOEUVRE DESIGNATOR.

REQUISITOS DE LA BASE DE DATOS AERONÁUTICA

AERONAUTICAL DATABASE REQUIREMENTS

PROCEDIMIENTOS DE APROXIMACIÓN POR INSTRUMENTOS
INSTRUMENT APPROACH PROCEDURES

VOR A

PUNTO	LAT	LONG	AZIMUT VERDADERO	DISTANCIA DME (NM)
POINT	LAT	LONG	TRUE BEARING	DME DISTANCE (NM)
OSPES (IAF)	402221.2N	0002049.0E	052.00°CTN	15.00 DME CTN
IF	402001.2N	0001653.5E	052.00°CTN	11.20 DME CTN
FAF	401656.7N	0001144.1E	052.00°CTN	6.20 DME CTN
MAPT	401403.2N	0000653.7E	052.00°CTN	1.50 DME CTN
Aproximación final de no precisión - Pendiente (Ángulo de descenso) Non-precision final approach - Slope (Descent angle)				-