



HOLDING, APPROACH AND DEPARTURE PROCEDURES

1. GENERAL

A list of the applicable rules can be consulted in section GEN 1.6. In the sections below, a descriptive summary is offered to help airspace users, although if there is any discrepancy, the Rule will prevail over the content of the AIP. The content of this AIP section does not fulfil the quality requirements.

Civil holding, approach and departure procedures are based on those contained in ICAO DOC 8168-OPS/611 (PANSOPS).

Military holding, approach and departure procedures are based on those contained in APATC-1 and ICAO DOC 8168-OPS/611 (PANS/OPS).

Some of these procedures are liable to speed adjusting; the indicated speed admits a tolerance of ± 10 kt. As soon as speed adjusting is no longer necessary aircraft will be stated: "no ATC speed restrictions".

Pilots shall comply as closely as possible with the procedures specified in AD 2 and ENR 6. These procedures are considered noise abatement preferential routings. ATC shall be informed if for any reason a procedure cannot be performed.

READ-BACK OF CLEARANCES AND SAFETY-RELATED INFORMATION

1. The flight crew shall read back to the air traffic controller safety-related parts of air traffic control (ATC) clearances and instructions which are transmitted by voice. The following items shall always be read back:
 - i. ATC route clearances,
 - ii. clearances and instructions to enter, land on, take off from, hold short of, cross, taxi and backtrack on any runway;
 - iii. runway-in-use, altimeter settings, SSR codes, newly assigned communication channels, level instructions, heading and speed instructions; and
 - iv. transition levels, whether issued by the controller or contained in ATIS broadcasts.
2. Other clearances or instructions, including conditional clearances and taxi instructions, shall be read-back or acknowledged in a manner to clearly indicate that they have been understood and will be complied with.
3. The controller shall listen to the read-back to ascertain that the clearance or instruction has been correctly acknowledged by the flight crew and shall take immediate action to correct any discrepancies revealed by the read-back.
4. Voice read-back of CPDLC messages shall not be required, unless otherwise specified by the ANSP.
5. SERA.14001 shall be applied when standardized phraseology is not useful and, on that basis, it is expected that pilots, ATS personnel and other ground personnel use everyday language, which besides the clarity required by the aforementioned section of SERA, shall be as concise as possible, to a level that meets requirements of ICAO with regard to language proficiency required by the applicable legislation on personnel licenses.

2. ARRIVING FLIGHTS

TERMINAL ZONE

Area control service will clear IFR flights landing within a TMA to a specified point and will instruct them to contact with the ATS unit providing approach service.

Aircraft entering or overflying a TMA shall keep the flight paths indicated in the appropriate charts; a complete description of the pertinent arrival procedure may be obtained, on request, from the ACC. Nevertheless, the suitable ATS unit will clear aircraft to proceed on more direct routes to specific points whenever traffic permitting.

ENR 6 and AD 2 sections contain the arrival and overflying, standardized or not, specific IFR/VFR procedures of those terminal areas where they are defined.

CONTROL AND AERODROME TRAFFIC ZONES



***VFR CROSSING:***

VFR aircraft wishing to cross a control zone, or aerodrome traffic zone, shall proceed as follows:

- a. Contact radio with APP/TWR shall be established in the appropriate frequency, at least, 5 minutes before reaching the first VFR reporting point, and shall notify to APP/TWR of its intention to cross on VFR the corresponding CTR/ATZ.
- b. Normally, when aircraft is over the VFR reporting point, APP/TWR shall clear to cross the CTR/ATZ and shall indicate the way to follow, the altitude to maintain and, if necessary, it will provide essential traffic information during the aircraft permanence within the airspace to be crossed.
- c. Aircraft shall report to APP/TWR the entry and exit of CTR/ATZ and must maintain watch in the appropriate frequency while it is within the airspace to be crossed.

VFR ARRIVALS:

VFR flights entering to land within a CTR shall establish contact radio with the appropriate ATS unit over the reporting points indicated in the charts and they shall request clearance to enter in the CTR.

In certain cases, aircraft shall perform holdings in the above mentioned points before entering the CTR.

Under no circumstances runway approach areas should be crossed without prior permission from control tower.

AD 2 and ENR 6 sections contain specific visual approach procedures.

3. DEPARTING FLIGHTS

GENERAL

Flights departing from controlled aerodromes will receive initial ATC clearance from the control tower. For IFR flights, the clearance limit will normally be the aerodrome of destination and detailed instructions will be issued with regard to routes, turnings, etc. after taking-off.

ATC AND STARTUP CLEARANCE VIA DATA LINK (DCL)

A. INTRODUCTION

The DCL service provides an additional data link means of requesting and issuing ATC and startup clearance for departing aircraft, not intended to replace, but to co-exist with, voice communications.

In the event of any discrepancy, voice communications will prevail over data link.

The DCL service is compliant with the EUROCAE specification ED-85A and is available to all ACARS-equipped aircraft with a contract with the air communications service provider (ACSP) SITA and/or ARINC.

B. DCL MESSAGES

The following operational messages may be sent by the pilot:

- RCD: Request Clearance Departure message, which implicitly includes startup request.
- CDA: Clearance Departure Echoback message, equivalent to read back.

The following operational message may be sent by the controller:

- CLD: Clearance Departure message, including in field 9 additional information on the extent of the startup clearance or instructions for requesting it via voice.

The following system message is sent automatically by the ATC system:

- FSM: Flight System Message, a logical response that may be positive or negative.

C. OPERATIONAL PROCEDURE





The decision to use DCL or voice communications is entirely at the discretion of the pilot and/or controller involved, but DCL use is highly recommended to optimize voice communications and to avoid frequency congestion.

C.1 Step 1

Pilot shall request DCL ATC and startup clearance in advance according to the startup procedures of the local regulation for the departure aerodrome (AD 2, item 20).

The RCD (Request Clearance Departure) message shall include the following data:

- Aircraft call sign, according to the filed flight plan (FPL).
- Departure aerodrome.
- Parking position.
- Destination aerodrome.
- Letter of the ATIS information received.
- ICAO designator of the aircraft type.

Free text contained in the RCD message will not be considered by ATC. Any specific request shall be transmitted by voice.

C.2 Step 2

Pilot will receive one of the following messages:

RCD RECEIVED REQUEST BEING PROCESSED STANDBY

FSM automatically sent by the ATC system when an RCD message is correctly processed.

RCD REJECTED REVERT TO VOICE PROCEDURES*
RCD REJECTED ERROR IN MESSAGE REVERT TO VOICE PROCEDURES*

FSM automatically sent by the ATC system when any inconsistency is detected within the RCD message.

RCD REJECTED FLIGHT PLAN NOT HELD REVERT TO VOICE PROCEDURES*

FSM automatically sent by the ATC system when there is any inconsistency with flight plan data.

RCD REJECTED REQUEST TOO LATE REVERT TO VOICE PROCEDURES*

FSM automatically sent by the ATC system when an RCD message has been sent later than the parameter time specified for the departure aerodrome.

RCD REJECTED REQUEST TOO EARLY SEND REQUEST NN MIN BEFORE EOBT
RCD REJECTED REQUEST TOO EARLY SEND REQUEST NN MIN BEFORE TOBT

FSM automatically sent by the ATC system when an RCD message has been sent earlier than the parameter time specified for the departure aerodrome.

RCD REJECTED REQUEST ALREADY RECEIVED STANDBY

FSM automatically sent by the ATC system when an RCD message has been received previously and the reply by ATC is pending.

* When a REVERT TO VOICE PROCEDURES message is received, data link communication will be terminated and the revert to voice procedure will apply (see section 4).

C.3 Step 3

When an RCD is correctly processed, the controller may:





a. Manually reject the request, sending the following FSM:

b. RCD RECEIVED CLEARANCE CANCELLED REVERT TO VOICE PROCEDURES*

* When a REVERT TO VOICE PROCEDURES message is received, data link communication will be terminated and the revert to voice procedure will apply (see section 4).

c. Accept the request, sending a CLD message with the following fields:

1. Aircraft call sign.
2. Destination aerodrome.
3. Departure runway.
4. Standard Instrument Departure (SID).
5. Note: The initial altitude will be the one specified in the SID description.
6. Mode A SSR code (SQUAWK).
7. ADT (Approved Departure Time).
8. Note: ADT=CTOT of the flight, if any.
9. Next frequency.
10. Letter of the current ATIS information.
11. Additional information, including the type of clearance issued in CLD message. Clearances requested via CLD will be granted based on time parameters from AIP local regulation of every aerodrome (AD 2, item 20).

STARTUP APPROVED

Startup approved and ATC clearance issued.

TSAT HHMM STAND BY ON XXX.XX FOR STARTUP

ATC clearance issued, TSAT information (CDM) and startup pending via voice.

TSAT HHMM READY MESSAGE SENT STAND BY ON XXX.XXX FOR STARTUP

ATC clearance issued (in the range TOBT $\pm$ 5'), READY message sent, TSAT (CDM) and startup information pending via voice.

CONTACT READY AT TOBT ON XXX.XXX

ATC clearance issued and startup request pending via voice according to TOBT (CDM).

STAND BY ON XXX.XXX FOR STARTUP

ATC clearance issued and startup pending via voice (no CDM).

CONTACT READY ACCORDING EOBT/CTOT ON XXX.XXX

ATC clearance issued and startup pending via voice according to EOBT/CTOT (n CDM).

C.4 Step 4

When a CLD message is received, pilot shall:

- a. Revert to voice to request a new clearance if any inconsistency is detected in the received message (see section 4).
- b. Respond via data link with a CDA (Departure Clearance Echoback) message if the clearance of the CLD message is considered correct.

If no CDA message is received within the time-out parameter, the CDA message is inconsistent with the previous CLD message, or an incorrect CDA message is received, data link communication will be terminated and one of the following FSM, respectively, will be received by the pilot:

RCD RECEIVED CLEARANCE CANCELLED REVERT TO VOICE PROCEDURES*

CDA REJECTED CLEARANCE CANCELLED REVERT TO VOICE PROCEDURES*

CDA REJECTED ERROR IN MESSAGE REVERT TO VOICE PROCEDURES*



* When a REVERT TO VOICE PROCEDURES message is received, data link communication will be terminated and the revert to voice procedure will apply (see section 4).

C.5 Step 5

When a correct CDA message is received, the ATC system will send the following FSM to the aircraft and terminate the data link communication:

CDA RECEIVED CLEARANCE CONFIRMED

D. REVERT TO VOICE PROCEDURE

Upon receiving a: “REVERT TO VOICE PROCEDURES” type of message, or if there is any inconsistency in the received clearance, the pilot shall contact the controller by voice to request a new clearance.

STANDARD INSTRUMENT DEPARTURES

The regulated departure procedures indicates, in an abbreviated way, the departure routes and the phraseology used by ATC in the initial clearances, in order to:

- a. simplify phraseology,
- b. give the pilot, prior take-off, the departure description in a written form.

The crossing flight levels/altitudes indicated in every clearance are the minimum at which each specific point must be crossed according to the route to be flown.

In order to provide vertical separation between aircraft, ATC may include in the initial clearance an specified flight level/altitude to be maintained up to a fixed point or time, that shall never be lower than those minimum ones above indicated.

A complete description of the pertinent departure procedure may be obtained by pilots when requested to the control tower prior to take-off.

The minimum climb gradient required for every SID is specified up to a flight level/altitude from which a minimum gradient of 3.3% must be maintained till the aircraft reaches the minimum altitude/flight level of the route to be flown.

A detailed description of these procedures is shown in ENR 6 and AD 2 sections.

4. OTHER RELEVANT INFORMATION AND PROCEDURES

4.1. HOLDINGS

Holding and approach procedures in use are based on the values and factors contained in Part II of the PANS-OPS.

Unless different conditions have been stablished for a specific procedure, the holding patterns shall be entered and flown as indicated below:

SPEED (Standard conditions)	
Up to FL140	170 kt (CAT A, B y H)
Up to FL140	230 kt
Above FL140 a FL200 inclusive	240 kt
Above FL200 a FL340 inclusive	265 kt
Above FL340	0.83 Mach

OUTBOUND TIME AND DISTANCE	
Up to FL140 inclusive	1 min
Above FL140	1 min 30 sec

DME distance is specified in the outbound leg where DME is available.

HOLDING PATTERN INCOMPATIBILITIES IN TERMINAL AREAS

COMPATIBILITY CRITERIA:

- Incompatibility has been considered up to FL240 (inclusive).
- The highest flight level or altitude on which both holding patterns are still compatible is indicated in the boxes.
- Empty boxes indicate that incompatibility does not occur up to the flight level considered.
- Headings in holding patterns are inbound.
- NC: Not compatible.

TMA ASTURIAS

CIRCUITO DE ESPERA // HOLDING PATTERN ON		ASTURIAS RWY 11		
		DVOR/DME VES	KUTIX	TUXAL
ASTURIAS RWY 11	DVOR/DME VES		NC	NC
	KUTIX	NC		FL120
	TUXAL	NC	FL120	

CIRCUITO DE ESPERA // HOLDING PATTERN ON		ASTURIAS RWY 29				
		NDB AV	DVOR/DME VES	LASIT	ROMIL	DORAR
ASTURIAS RWY 29	NDB AV		NC	NC	NC	NC
	DVOR/DME VES	NC		NC	NC	NC
	LASIT	NC	NC		FL070	–
	ROMIL	NC	NC	FL070		FL140
	DORAR	NC	NC	–	FL140	

NOTA // NOTE [TMA ASTURIAS]:
La incompatibilidad se ha considerado hasta FL155 (inclusive). // Incompatibility has been considered up to FL155 (inclusive).
En el caso de existir esperas RNAV y convencionales sobre un mismo waypoint, se ha considerado la más restrictiva. // In the case of RNAV and conventional waits on the same waypoint, it has been considered the most restrictive.

TMA ALMERÍA

CIRCUITO DE ESPERA // HOLDING PATTERN ON		ALMERÍA-LEAM									
		ROBIP	MAXET	NDB L AM 074°	VOR/DME AMR 285°	RIXAL	NIDON	MOLUV (RNAV)	ASNEP (RNAV)	NIDON (RNAV)	RIXAL (RNAV)
ALMERÍA-LEAM	ROBIP		FL100	NC	FL080	–	–	NC	–	–	–
	MAXET	FL100		FL090	NC	5000	–	NC	–	–	6000
	NDB L AM 074°	NC	FL090		NC	NC	NC	NC	NC (1)	NC	NC
	VOR/DME AMR 285°	FL080	NC	NC		NC	FL070	6000	NC (1)	NC	NC
	RIXAL	–	5000	NC	NC		–	–	–	–	NC
	NIDON	–	–	NC	FL070	–		–	NC (1)	NC	–
	MOLUV (RNAV)	NC	NC	NC	6000	–	–		FL100	–	–
	ASNEP (RNAV)	–	–	NC (1)	NC (1)	–	NC (1)	FL100		NC (1)	–
	NIDON (RNAV)	–	–	NC	NC	–	NC	–	NC (1)		FL130
	RIXAL (RNAV)	–	6000	NC	NC	NC	–	–	–	FL130	

NOTA // NOTE [TMA ALMERÍA]:
La espera ASNEP está restringida a nivel de vuelo mínimo FL090 sujeta a la actividad LER63, LER156 y LED36, y nivel de vuelo mínimo FL110 sujeta a la actividad LER63 y LED36. // ASNEP holding pattern is restricted to FL090 minimum subject to LER63, LER156 and LED36, and to FL110 minimum subject to LER63 and LED36.

TMA BARCELONA: NORTH CONFIGURATION

CIRCUITO DE ESPERA / HOLDING PATTERN ON		BARCELONA/Usap Tardellas Barcelona-EI Put															GIRONA					REUS					LLEIDA/Raguere					ANDORRA/ La Seu D'Urgell								
		CONFIGURACIÓN NORTE / NORTH CONFIGURATION															RWY					RWY					RWY					RWY								
		BGR	CLE	CUTE	ELLH	SLL	TRIGO	PERIS	PUJH	SADEM	KANWU	KOSIT	LESSA	MEDJH	OSTUR	RULOS	USSOF	UTHAN	VLA	01	01	01	19	19	19	07	07	0705	25	25	0705	1301	31	31	31	31	31	03		
DVOR CLE	OKETA	DVOR GBR 194°	DVOR GBR 034°	BANOL	NDB GBN	KERP	D1SET	VOR RES	DVOR VLA	NDB RUS 070°	NDB ZOP	RUS	VOR LLE	NDB LLD	ROVAP PEN	VOR LLE PEN	NDB LLD PEN	ROVAP PEN	UPISA																					
BARCELONA/Usap Tardellas Barcelona-EI Put	CONFIGURACIÓN NORTE / NORTH CONFIGURATION	BGR	NC	NC	-	-	-	-	-	-	-	-	-	-	-	NC	FL160	-	FL200	NC	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-					
		CLE	NC	FL140	FL150	FL160	-	-	-	-	-	FL180	FL100	-	-	FL200	-	NC	NC	-	NC	NC	NC	FL140	NC	-	-	-	-	-	-	-	-	-	-	-				
		CUTE	NC	FL140	FL230	-	-	-	-	-	-	FL230	-	-	-	FL160	NC	-	FL200	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-				
		ELLH	-	FL160	FL230	-	-	-	-	-	-	NC	-	-	-	-	NC	-	FL230	-	FL200	-	-	-	FL230	-	-	-	-	-	-	-	-	-	-	-				
		SLL	-	FL160	-	-	-	-	-	-	FL200	-	-	-	NC	FL140	FL160	-	FL140	FL100	NC	-	-	FL170	-	-	-	FL160	NC	-	FL170	-	-	FL200	-	-	-	FL160		
		TRIGO	-	-	-	-	FL200	NC	-	-	-	-	-	NC	-	-	-	-	-	-	-	-	-	-	-	FL200	-	FL170	-	-	NC	NC	NC	NC	FL130	NC	NC			
		PERIS	-	-	-	-	FL200	NC	-	-	-	FL200	-	-	NC	-	-	-	FL200	-	-	-	-	-	-	NC	FL180	NC	-	FL200	NC	NC	FL120	FL150	NC	NC				
		PUJH	-	-	-	-	-	-	FL200	-	NC	-	-	NC	-	-	-	-	NC	-	-	-	-	-	-	NC	NC	-	NC	NC	NC	FL200	NC	FL200	NC	FL200	-			
		SADEM	-	-	-	-	-	-	-	-	-	-	NC	-	-	FL200	-	-	FL200	-	-	FL210	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
		KANWU	-	-	-	-	-	-	NC	-	-	-	-	-	-	-	-	FL230	-	-	-	-	-	-	-	NC	-	-	FL180	-	NC	FL180	-	-	-	-	-			
		KOSIT	-	FL180	FL230	NC	NC	-	-	-	-	-	-	-	-	-	-	NC	-	FL140	-	FL200	FL200	-	FL230	-	-	-	-	FL190	-	-	-	-	-	-	-			
		LESSA	-	FL100	-	-	-	-	-	NC	-	-	-	-	NC	NC	NC	-	-	FL080	FL160	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
		MEDJH	-	-	-	-	FL180	NC	NC	NC	-	-	-	-	-	-	-	-	NC	-	-	-	-	-	-	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC			
		OSTUR	-	-	-	-	-	-	-	-	FL200	-	-	NC	-	-	FL200	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
		RULOS	-	FL200	-	-	-	-	-	-	-	-	-	NC	-	FL200	NC	-	-	FL220	FL140	-	-	-	FL220	-	-	-	FL200	FL220	-	FL200	-	-	-	-	-			
		NEPAL	-	-	-	-	-	-	-	-	-	FL230	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
		USSOF	NC	NC	FL160	-	-	-	-	FL200	-	-	NC	-	-	-	-	-	FL180	-	NC	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-			
		UTHAN	FL160	NC	NC	NC	FL140	-	-	-	-	-	NC	-	-	-	-	FL160	-	-	NC	FL170	NC	NC	FL120	NC	-	-	-	-	FL210	-	-	-	-	-	-			
		VLA	-	-	-	-	-	FL100	-	FL200	NC	-	FL210	-	-	NC	-	FL220	-	-	FL230	-	-	-	-	-	FL140	FL140	NC	NC	NC	NC	NC	FL230	FL180	FL180	FL200	FL160	FL120	
GIRONA	RWY	01	DVOR CLE	FL200	NC	-	FL230	NC	-	-	-	-	FL140	FL090	-	-	FL140	-	NC	NC	FL230	NC	FL080	NC	FL210	FL160	-	-	-	FL160	-	-	-	-	-	-				
		01	OKETA	NC	NC	FL200	-	-	-	-	FL210	-	-	FL180	-	-	-	NC	FL170	-	NC	NC	NC	NC	FL160	FL080	-	-	-	-	-	-	-	-	-	-				
		01	DVOR GBR 194°	NC	NC	NC	FL200	-	-	-	-	-	FL200	-	-	-	-	NC	NC	-	FL080	NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-			
		19	DVOR GBR 034°	NC	NC	NC	NC	-	FL170	-	-	-	-	FL200	FL160	-	-	FL220	-	NC	NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-			
		19	BANOL	NC	FL140	NC	-	-	-	-	-	-	-	-	-	-	NC	FL130	-	FL210	FL160	NC	NC	-	NC	-	-	-	-	-	-	-	-	-	-	-	-			
19	NDB GBN	NC	NC	NC	FL230	-	-	-	-	-	-	FL230	-	-	-	NC	NC	-	FL160	FL080	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-					
REUS	RWY	07	KERP	-	-	-	-	-	-	NC	-	-	NC	-	-	-	-	-	FL140	-	-	-	-	-	-	-	NC	NC	FL180	NC	NC	-	-	FL130	-	-	FL200	-		
		07	D1SET	-	-	-	-	-	FL200	NC	NC	-	-	NC	-	-	-	-	-	FL140	-	-	-	-	-	-	NC	NC	-	NC	NC	FL110	NC	FL080	FL130	NC	NC			
		0705	VOR RES	-	-	-	-	-	FL160	-	FL190	NC	-	FL180	-	NC	-	-	NC	-	-	-	-	-	-	NC	NC	-	NC	NC	NC	FL210	FL140	FL170	-	FL210	FL200	-		
		25	DVOR VLA	-	-	-	-	NC	FL170	NC	-	-	-	FL190	-	NC	-	FL220	-	FL210	NC	FL160	-	-	-	-	FL180	-	NC	-	FL110	NC	-	-	FL180	-	-	FL180	FL180	
		25	NDB RUS 070°	-	-	-	-	-	-	NC	-	NC	-	-	NC	-	-	-	-	NC	-	-	-	-	-	-	NC	NC	NC	NC	FL110	-	NC	FL170	FL120	FL200	-	FL140	FL240	-
0705	NDB RUS 250°	-	-	-	-	-	-	FL170	-	FL200	NC	-	FL180	-	NC	-	FL200	-	-	NC	-	-	-	-	NC	NC	NC	NC	NC	-	FL200	FL140	FL190	-	FL200	FL210	FL190			
LLEIDA/Raguere	RWY	1301	VOR LLE	-	-	-	-	NC	NC	FL180	-	-	-	NC	-	-	-	-	FL230	-	-	-	-	-	-	-	-	FL110	FL210	-	-	FL170	FL200	-	NC	NC	NC	NC	NC	FL140
		31	NDB LRD	-	-	-	-	-	NC	NC	NC	-	-	-	NC	-	-	-	-	FL180	-	-	-	-	-	-	FL130	NC	FL140	-	-	FL120	FL140	NC	-	NC	NC	NC	NC	FL210
		31	ROVAP	-	-	-	-	-	FL200	NC	NC	FL200	-	-	-	NC	-	-	-	FL160	-	-	-	-	-	-	-	FL080	FL170	FL180	FL200	FL190	NC	NC	-	NC	NC	NC	NC	NC
		31	VOR LLE PEN	-	-	-	-	-	NC	FL120	FL200	-	-	-	NC	-	-	-	-	FL200	-	-	-	-	-	-	-	FL120	-	-	-	-	-	NC	NC	NC	-	NC	NC	FL140
		31	NDB LRD PEN	-	-	-	-	-	-	FL120	FL160	NC	-	-	-	NC	-	-	-	-	FL160	-	-	-	-	-	-	-	FL200	NC	FL210	-	-	FL140	FL200	NC	NC	NC	-	NC
31	ROVAP PEN	-	-	-	-	-	-	NC	NC	FL200	-	-	-	NC	-	-	-	-	FL120	-	-	-	-	-	-	-	NC	FL200	FL180	FL240	FL210	NC	NC	NC	NC	NC	-	NC		
ANDORRA/ La Seu D'Urgell	RWY	03	UPISA	-	-	-	-	FL180	NC	NC	-	-	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL180	-	FL190	FL140	FL210	NC	FL140	FL200	NC	-		



TMA BARCELONA: EAST CONFIGURATION

GRUPO DE ESPERA / HOLDING PATTERN ON		BARCELONA/Josep Torredellas Barcelona-EI Prut														GIRONA					REUS										LLEIDA/ Alguine							ANDORRA/ La Seu D' Urgel	
		CONFIGURACIÓN ESTE														RWY					RWY										RWY							RWY	
		BGR	BOLDE	UTHAN	SLL	SLL Falso	KANWU	KOST	YUTHU	OSTUR	VIBM	RUBOT	PAPOS	PUJH	NEPAL	VLA	LRD	RES	01	01	01	19	19	19	07	07	0705	25	25	0705	1301	31	31	31	31	31	31	08	
		DIVOR CLE	OKETA	DIVOR GSR 194°	DIVOR GSR 054°	BANOL	NDB GRN	KERP	DISET	VOR RES	DIVOR VLA	NDB BUS 070°	NDB SHF	RUS	VOR LLE	NDB LRD	ROVAP	VOR LLE PBN	NDB LRD PBN	ROVAP PBN	UPISA																		
BARCELONA/Josep Torredellas Barcelona-EI Prut	CONFIGURACIÓN ESTE	BGR	-	FL160	-	-	-	-	-	-	-	-	-	-	-	-	-	FL200	NC	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-		
		BOLDE	-	FL180	NC	NC	-	NC	-	-	-	-	-	-	-	NC	-	-	FL200	-	-	-	-	-	-	-	-	FL200	NC	-	FL200	-	-	FL140	-	-	FL140	NC	
		UTHAN	FL160	FL160	-	NC	NC	-	NC	-	-	-	-	-	-	-	-	-	NC	FL170	NC	NC	FL120	NC	-	-	-	FL210	-	-	-	-	-	-	-	-	-	-	
		SLL	-	NC	NC	-	NC	-	NC	-	-	FL220	-	-	-	FL190	-	NC	-	FL220	FL140	-	-	-	-	-	FL200	FL090	-	FL220	-	-	-	-	-	-	-		
		SLL Falso	-	NC	NC	NC	-	NC	-	-	FL230	-	-	-	-	FL190	-	NC	-	FL200	FL140	-	-	-	-	-	-	FL110	-	-	-	-	-	-	-	-	-	-	
		KANWU	-	-	-	-	-	-	-	-	-	NC	NC	NC	-	-	-	NC	-	-	-	-	-	-	-	NC	-	FL180	-	NC	FL180	-	-	-	-	-	-	-	
		KOST	-	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	FL140	-	FL200	FL200	-	FL230	-	-	-	-	FL180	-	-	-	-	-	-	-	-	-	-	
		YUTHU	-	-	-	-	-	-	-	-	NC	FL200	-	-	-	-	-	-	-	FL210	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
		OSTUR	-	-	-	-	-	-	NC	NC	-	-	-	-	-	FL210	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		VIBM	-	-	-	FL220	FL230	-	-	FL200	NC	FL180	-	-	NC	-	-	FL210	-	-	-	-	-	-	-	-	-	FL230	-	-	-	-	-	-	-	-	-	-	-
		RUBOT	-	-	-	-	NC	-	-	-	FL160	NC	FL200	NC	FL170	-	FL100	-	-	-	-	-	-	-	-	-	FL130	-	6000	FL130	FL140	6000	-	-	-	-	-	-	-
		PAPOS	-	-	-	-	NC	-	-	-	-	NC	-	-	NC	-	-	-	-	-	-	-	-	-	-	-	FL160	-	FL210	-	-	FL200	-	-	-	-	-	-	-
		PUJH	-	-	-	-	NC	-	-	-	-	FL200	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	-	NC	NC	FL180	NC	-	FL200	NC	FL200	-	-
		NEPAL	-	-	-	-	-	-	-	-	FL210	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL220	-	-	-	-	-	-	-	-	-	-
		VLA	-	NC	-	FL190	FL150	-	-	-	-	FL170	-	FL190	-	FL200	NC	FL230	-	-	-	-	-	-	-	FL200	FL140	NC	NC	NC	NC	FL190	FL160	FL120	FL180	FL160	FL120	FL140	
		LRD	-	-	-	-	-	-	-	-	-	-	NC	-	FL200	NC	-	-	-	-	-	-	-	-	-	NC	-	-	FL200	-	NC	NC	NC	NC	NC	NC	NC	-	-
		RES	-	-	-	-	NC	-	-	-	-	FL100	-	NC	NC	NC	-	-	-	-	-	-	-	-	-	NC	NC	NC	FL100	NC	NC	FL150	FL080	FL140	FL180	FL110	FL140	-	-
GIRONA	RWY	01	DIVOR CLE	FL200	FL200	NC	NC	NC	-	FL140	-	-	FL210	-	-	-	FL230	-	-	NC	FL090	NC	FL210	FL160	-	-	-	FL160	-	-	-	-	-	-	-	-	-	-	
		01	OKETA	NC	-	FL170	-	-	-	-	FL210	-	-	-	-	-	-	-	NC	-	NC	NC	FL160	FL080	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		01	DIVOR GSR 194°	NC	-	NC	FL220	FL200	-	FL200	-	-	-	-	-	-	-	-	FL090	NC	-	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		19	DIVOR GSR 054°	NC	-	NC	FL140	FL140	-	FL200	-	-	-	-	-	-	-	-	NC	NC	NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		19	BANOL	NC	-	FL120	-	-	-	-	-	-	-	-	-	-	-	-	FL210	FL160	NC	NC	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		19	NDB GRN	NC	-	NC	-	-	-	FL230	-	-	-	-	-	-	-	-	FL160	FL080	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
REUS	RWY	07	KERP	-	-	-	-	NC	-	-	-	FL130	FL160	NC	-	FL300	-	NC	-	-	-	-	-	-	NC	NC	FL180	NC	NC	-	FL130	-	-	FL220	-	-			
		07	DISET	-	-	-	-	-	-	-	-	-	-	-	NC	-	FL140	NC	NC	-	-	-	-	-	NC	-	NC	-	NC	NC	FL110	NC	FL080	FL140	NC	NC	-	-	
		0705	VOR RES	-	FL200	-	FL200	-	FL180	-	-	FL230	6000	FL210	NC	FL220	NC	-	NC	-	-	-	-	-	NC	NC	-	NC	NC	NC	FL210	FL140	FL170	-	FL210	FL200	-	-	
		25	DIVOR VLA	-	NC	FL210	FL090	FL110	-	FL180	-	-	FL130	-	-	NC	-	FL100	FL160	-	-	-	-	-	-	FL180	-	NC	-	FL110	NC	-	-	FL180	-	-	FL180	FL170	
		25	NDB BUS 070°	-	-	-	-	NC	-	-	-	FL140	-	NC	-	NC	FL200	NC	-	-	-	-	-	-	-	NC	NC	NC	NC	FL110	NC	FL170	FL120	FL200	-	FL140	-	-	
		0705	NDB BUS 250°	-	FL200	-	FL220	-	FL180	-	-	-	6000	FL200	NC	FL220	NC	-	NC	-	-	-	-	-	-	NC	NC	NC	NC	NC	-	FL200	FL140	FL190	-	FL200	FL210	FL190	
LLEIDA/Alguine	RWY	1301	VOR LLE	-	-	-	-	-	-	-	-	-	-	FL180	-	FL190	NC	FL150	-	-	-	-	-	-	-	FL110	FL210	-	FL170	FL200	-	NC	NC	NC	NC	NC	NC	FL140	
		31	NDB LRD	-	-	-	-	-	-	-	-	-	-	NC	-	FL160	NC	FL090	-	-	-	-	-	-	FL130	NC	FL140	-	FL120	FL140	NC	-	NC	NC	NC	NC	NC	FL210	
		31	ROVAP	-	FL140	-	-	-	-	-	-	-	-	-	-	FL120	NC	FL140	-	-	-	-	-	-	-	FL080	FL170	FL180	FL200	FL190	NC	NC	-	NC	NC	NC	NC	NC	-
		31	VOR LLE PBN	-	-	-	-	-	-	-	-	-	FL200	-	FL180	NC	FL160	-	-	-	-	-	-	-	-	FL140	-	-	-	-	-	NC	NC	NC	-	NC	NC	FL140	
		31	NDB LRD PBN	-	-	-	-	-	-	-	-	-	NC	-	FL160	NC	FL110	-	-	-	-	-	-	-	-	FL220	NC	FL210	-	FL140	FL200	NC	NC	NC	NC	-	NC	FL200	
		31	ROVAP PBN	-	FL140	-	-	-	-	-	-	-	-	FL200	-	FL120	NC	FL140	-	-	-	-	-	-	-	-	NC	FL200	FL180	-	FL210	NC	NC	NC	NC	NC	-	NC	
		ANDORRA/ La Seu D' Urgel	RWY	03	UPISA	-	NC	-	-	-	-	-	-	-	-	-	FL140	-	-	-	-	-	-	-	-	-	-	-	-	FL170	-	FL190	FL140	FL210	NC	FL140	FL200	NC	-



TMA BARCELONA: WEST CONFIGURATION

CIRCUITO DE ESPERA / HOLDING PATTERN ON				BARCELONA/Usap Tardellas Barcelona-EI Put																GIRONA						REUS						LLEIDA/Ribera						ANDORRA/ La Seu D'Urgel	
				CONFIGURACIÓN OESTE																RWY						RWY						RWY						RWY	
				BGR	CLE	CUTE	ELLH	SLL	TROD	PERIS	PUJH	SADEM	KANWU	KOSIT	LESSA	MEDJH	OSTUR	RULOS	USOOF	UTHAN	VLA	01	01	01	19	19	19	07	07	0705	25	25	0705	1301	31	31	31	31	31
DVOR CLE	OKETA	DVOR GBR 194	DVOR GBR 034	BANOL	NDB GBN	KERP	DISET	VOR RES	DVOR VLA	NDB RUS 070	NDB ZUP	RUS	VOR LLE	NDB LLD	ROVAP PBN	VOR LLE PBN	NDB LLD PBN	ROVAP PBN	UPISA																				
BARCELONA/Usap Tardellas Barcelona-EI Put	CONFIGURACIÓN OESTE	BGR	NC	NC	-	-	-	-	-	-	-	-	-	-	-	NC	FL160	-	FL200	NC	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-			
		CLE	NC	FL140	FL150	FL160	-	-	-	-	-	FL180	FL100	-	-	FL200	-	NC	NC	-	NC	NC	NC	FL140	NC	-	-	-	-	-	-	-	-	-	-	-	-		
		CUTE	NC	FL140	FL230	-	-	-	-	-	-	FL230	-	-	-	FL180	NC	-	FL200	NC	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-		
		ELLH	-	FL160	FL230	-	-	-	-	-	-	NC	-	-	-	-	NC	-	FL230	-	FL200	-	-	FL230	-	-	-	-	-	-	-	-	-	-	-	-	-		
		SLL	-	FL180	-	-	-	-	-	-	NC	FL140	FL180	-	FL140	-	FL140	FL100	NC	-	-	-	FL170	-	-	-	-	FL180	NC	-	FL170	-	-	FL200	-	-	-	FL180	
		TROD	-	-	-	-	FL200	NC	-	-	-	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	FL200	-	FL170	-	-	NC	NC	NC	NC	FL130	NC	NC		
		PERIS	-	-	-	-	FL200	NC	-	-	-	-	NC	-	-	-	-	-	FL200	-	-	-	-	-	NC	FL180	NC	-	FL200	NC	NC	NC	NC	FL120	FL150	NC	NC		
		PUJH	-	-	-	-	-	FL200	-	-	NC	-	-	NC	-	-	-	-	NC	-	-	-	-	-	NC	NC	NC	-	NC	NC	NC	FL200	NC	FL200	NC	FL200	-	-	
		SADEM	-	-	-	-	-	-	-	-	-	NC	-	-	FL200	-	-	FL200	-	-	FL210	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
		KANWU	-	-	-	-	-	-	NC	-	-	-	-	-	-	-	FL230	-	-	-	-	-	-	-	NC	-	-	FL180	-	NC	FL180	-	-	-	-	-	-	-	
		KOSIT	-	FL180	FL230	NC	NC	-	-	-	-	-	-	-	-	-	NC	-	FL140	-	FL200	-	FL200	-	FL230	-	-	-	FL190	-	-	-	-	-	-	-	-		
		LESSA	-	FL100	-	-	-	-	-	NC	-	-	-	NC	NC	-	NC	-	FL080	FL180	-	FL160	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		MEDJH	-	-	-	-	FL180	NC	NC	NC	-	-	-	-	-	-	-	-	NC	-	-	-	-	-	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC	NC	
		OSTUR	-	-	-	-	-	-	-	-	FL200	-	-	NC	-	-	FL200	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		RULOS	-	FL200	-	-	-	-	-	-	-	-	NC	-	FL200	-	-	FL220	FL140	-	-	-	FL220	-	-	-	-	FL200	FL220	-	FL200	-	-	-	-	-	-	-	
		NEPAL	-	-	-	-	-	-	-	-	FL230	-	-	-	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
		USOOF	NC	NC	FL160	-	-	-	-	FL200	-	-	NC	-	-	-	-	-	FL180	-	NC	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	
		UTHAN	FL180	NC	NC	NC	FL140	-	-	-	-	-	NC	-	-	-	-	FL180	-	NC	FL170	NC	NC	FL120	NC	-	-	-	FL210	-	-	-	-	-	-	-	-	-	
VLA	-	-	-	-	-	-	FL100	-	FL200	NC	FL210	-	-	NC	-	FL220	-	-	FL230	-	-	-	-	-	FL140	FL140	NC	NC	NC	NC	NC	FL230	FL180	FL200	FL180	FL120	-		
GIRONA	RWY	01	DVOR CLE	FL200	NC	-	FL230	NC	-	-	-	-	FL140	FL090	-	-	FL140	-	NC	NC	FL230	NC	FL080	NC	FL210	FL160	-	-	FL160	-	-	-	-	-	-	-	-		
		01	OKETA	NC	NC	FL200	-	-	-	-	-	FL210	-	-	-	FL180	-	-	-	NC	FL170	-	NC	NC	NC	FL180	FL080	-	-	-	-	-	-	-	-	-	-		
		01	DVOR GBR 194	NC	NC	NC	FL200	-	-	-	-	-	-	-	FL200	-	-	-	-	NC	NC	-	FL080	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-		
		19	DVOR GBR 034	NC	NC	NC	-	-	-	-	-	-	-	-	FL200	FL180	-	-	-	NC	NC	NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-		
		19	BANOL	NC	FL140	NC	-	-	-	-	-	-	-	-	-	-	NC	FL130	-	FL210	FL160	NC	NC	-	NC	-	-	-	-	-	-	-	-	-	-	-	-		
		19	NDB GBN	NC	NC	NC	FL230	-	-	-	-	-	-	FL230	-	-	-	NC	NC	-	FL160	FL080	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-		
REUS	RWY	07	KERP	-	-	-	-	-	-	NC	-	-	NC	-	-	-	-	FL140	-	-	-	-	-	-	-	NC	NC	FL180	NC	NC	-	-	FL130	-	-	FL200	-		
		07	DISET	-	-	-	-	-	FL200	NC	NC	-	-	NC	-	-	-	-	FL140	-	-	-	-	-	NC	NC	NC	-	NC	NC	FL110	NC	FL080	FL130	NC	NC	-		
		0705	VOR RES	-	-	-	-	-	FL160	-	FL190	NC	-	-	FL180	-	NC	-	-	-	-	-	-	NC	NC	-	NC	NC	NC	NC	FL210	FL140	FL170	-	FL210	FL200	-		
		25	DVOR VLA	-	-	-	-	-	NC	FL170	NC	-	-	-	FL190	-	NC	-	FL220	-	-	FL210	NC	FL160	-	-	-	FL180	-	NC	-	FL110	NC	-	-	FL180	-	FL180	
		25	NDB RUS 070	-	-	-	-	-	-	NC	-	NC	-	-	NC	-	-	-	-	NC	-	-	-	-	-	NC	NC	NC	NC	FL110	-	NC	FL170	FL120	FL200	-	FL140	FL240	-
		0705	NDB RUS 250	-	-	-	-	-	-	FL170	-	FL200	NC	-	FL180	-	NC	-	FL200	-	-	NC	-	-	-	NC	NC	NC	NC	NC	-	FL200	FL140	FL190	-	FL200	FL210	FL190	
LLEIDA/Ribera	RWY	1301	VOR LLE	-	-	-	-	-	NC	NC	FL180	-	-	-	NC	-	-	-	FL230	-	-	-	-	-	-	-	FL110	FL210	-	-	FL170	FL200	-	NC	NC	NC	NC	NC	FL140
		31	NDB LLD	-	-	-	-	-	NC	NC	NC	-	-	-	NC	-	-	-	-	FL180	-	-	-	-	-	FL130	NC	FL140	-	FL120	FL140	NC	-	NC	NC	NC	NC	FL210	
		31	ROVAP	-	-	-	-	-	FL200	NC	NC	FL200	-	-	-	NC	-	-	-	-	FL160	-	-	-	-	-	FL080	FL170	FL180	FL200	FL190	NC	NC	NC	-	NC	NC	NC	NC
		31	VOR LLE PBN	-	-	-	-	-	NC	FL120	FL200	-	-	-	-	NC	-	-	-	-	FL200	-	-	-	-	-	FL120	-	-	-	-	-	NC	NC	NC	-	NC	NC	FL140
		31	NDB LLD PBN	-	-	-	-	-	-	FL120	FL160	NC	-	-	-	NC	-	-	-	-	FL160	-	-	-	-	-	FL200	NC	FL210	-	-	FL140	FL200	NC	NC	NC	-	NC	FL200
		31	ROVAP PBN	-	-	-	-	-	-	NC	NC	FL200	-	-	-	NC	-	-	-	-	FL120	-	-	-	-	-	NC	FL200	FL180	FL240	FL210	NC	NC	NC	NC	NC	-	NC	
ANDORRA/ La Seu D'Urgel	RWY	03	UPISA	-	-	-	-	-	FL180	NC	NC	-	-	-	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	FL180	-	FL190	FL140	FL210	NC	FL140	FL200	NC	

TMA BILBAO, CTA LOGROÑO, CTA PAMPLONA, CTA SAN SEBASTIÁN, TMA SANTANDER, CTA VITORIA

TMA BILBAO		CTA LOGROÑO		CTA PAMPLONA		CTA SAN SEBASTIÁN		TMA SANTANDER		CTA VITORIA	
1	2	3	4	5	6	7	8	9	10	11	12
13	14	15	16	17	18	19	20	21	22	23	24
25	26	27	28	29	30	31	32	33	34	35	36
37	38	39	40	41	42	43	44	45	46	47	48
49	50	51	52	53	54	55	56	57	58	59	60
61	62	63	64	65	66	67	68	69	70	71	72
73	74	75	76	77	78	79	80	81	82	83	84
85	86	87	88	89	90	91	92	93	94	95	96
97	98	99	100	101	102	103	104	105	106	107	108
109	110	111	112	113	114	115	116	117	118	119	120
121	122	123	124	125	126	127	128	129	130	131	132
133	134	135	136	137	138	139	140	141	142	143	144
145	146	147	148	149	150	151	152	153	154	155	156
157	158	159	160	161	162	163	164	165	166	167	168
169	170	171	172	173	174	175	176	177	178	179	180
181	182	183	184	185	186	187	188	189	190	191	192
193	194	195	196	197	198	199	200	201	202	203	204
205	206	207	208	209	210	211	212	213	214	215	216
217	218	219	220	221	222	223	224	225	226	227	228
229	230	231	232	233	234	235	236	237	238	239	240
241	242	243	244	245	246	247	248	249	250	251	252
253	254	255	256	257	258	259	260	261	262	263	264
265	266	267	268	269	270	271	272	273	274	275	276
277	278	279	280	281	282	283	284	285	286	287	288
289	290	291	292	293	294	295	296	297	298	299	300
301	302	303	304	305	306	307	308	309	310	311	312
313	314	315	316	317	318	319	320	321	322	323	324
325	326	327	328	329	330	331	332	333	334	335	336
337	338	339	340	341	342	343	344	345	346	347	348
349	350	351	352	353	354	355	356	357	358	359	360
361	362	363	364	365	366	367	368	369	370	371	372
373	374	375	376	377	378	379	380	381	382	383	384
385	386	387	388	389	390	391	392	393	394	395	396
397	398	399	400	401	402	403	404	405	406	407	408
409	410	411	412	413	414	415	416	417	418	419	420
421	422	423	424	425	426	427	428	429	430	431	432
433	434	435	436	437	438	439	440	441	442	443	444
445	446	447	448	449	450	451	452	453	454	455	456
457	458	459	460	461	462	463	464	465	466	467	468
469	470	471	472	473	474	475	476	477	478	479	480
481	482	483	484	485	486	487	488	489	490	491	492
493	494	495	496	497	498	499	500	501	502	503	504
505	506	507	508	509	510	511	512	513	514	515	516
517	518	519	520	521	522	523	524	525	526	527	528
529	530	531	532	533	534	535	536	537	538	539	540
541	542	543	544	545	546	547	548	549	550	551	552
553	554	555	556	557	558	559	560	561	562	563	564
565	566	567	568	569	570	571	572	573	574	575	576
577	578	579	580	581	582	583	584	585	586	587	588
589	590	591	592	593	594	595	596	597	598	599	600
601	602	603	604	605	606	607	608	609	610	611	612
613	614	615	616	617	618	619	620	621	622	623	624
625	626	627	628	629	630	631	632	633	634	635	636
637	638	639	640	641	642	643	644	645	646	647	648
649	650	651	652	653	654	655	656	657	658	659	660
661	662	663	664	665	666	667	668	669	670	671	672
673	674	675	676	677	678	679	680	681	682	683	684
685	686	687	688	689	690	691	692	693	694	695	696
697	698	699	700	701	702	703	704	705	706	707	708
709	710	711	712	713	714	715	716	717	718	719	720
721	722	723	724	725	726	727	728	729	730	731	732
733	734	735	736	737	738	739	740	741	742	743	744
745	746	747	748	749	750	751	752	753	754	755	756
757	758	759	760	761	762	763	764	765	766	767	768
769	770	771	772	773	774	775	776	777	778	779	780
781	782	783	784	785	786	787	788	789	790	791	792
793	794	795	796	797	798	799	800	801	802	803	804
805	806	807	808	809	810	811	812	813	814	815	816
817	818	819	820	821	822	823	824	825	826	827	828
829	830	831	832	833	834	835	836	837	838	839	840
841	842	843	844	845	846	847	848	849	850	851	852
853	854	855	856	857	858	859	860	861	862	863	864
865	866	867	868	869	870	871	872	873	874	875	876
877	878	879	880	881	882	883	884	885	886	887	888
889	890	891	892	893	894	895	896	897	898	899	900
901	902	903	904	905	906	907	908	909	910	911	912
913	914	915	916	917	918	919	920	921	922	923	924
925	926	927	928	929	930	931	932	933	934	935	936
937	938	939	940	941	942	943	944	945	946	947	948
949	950	951	952	953	954	955	956	957	958	959	960
961	962	963	964	965	966	967	968	969	970	971	972
973	974	975	976	977	978	979	980	981	982	983	984
985	986	987	988	989	990	991	992	993	994	995	996
997	998	999	1000	1001	1002	1003	1004	1005	1006	1007	1008
1009	1010	1011	1012	1013	1014	1015	1016	1017	1018	1019	1020
1021	1022	1023	1024	1025	1026	1027	1028	1029	1030	1031	1032
1033	1034	1035	1036	1037	1038	1039	1040	1041	1042	1043	1044
1045	1046	1047	1048	1049	1050	1051	1052	1053	1054	1055	1056
1057	1058	1059	1060	1061	1062	1063	1064	1065	1066	1067	1068
1069	1070	1071	1072	1073	1074	1075	1076	1077	1078	1079	1080
1081	1082	1083	1084	1085	1086	1087	1088	1089	1090	1091	1092
1093	1094	1095	1096	1097	1098	1099	1100	1101	1102	1103	1104
1105	1106	1107	1108	1109	1110	1111	1112	1113	1114	1115	1116
1117	1118	1119	1120	1121	1122	1123	1124	1125	1126	1127	1128
1129	1130	1131	1132	1133	1134	1135	1136	1137	1138	1139	1140
1141	1142	1143	1144	1145	1146	1147	1148	1149	1150	1151	1152
1153	1154	1155	1156	1157	1158	1159	1160	1161	1162	1163	1164
1165	1166	1167	1168	1169	1170	1171	1172	1173	1174	1175	1176
1177	1178	1179	1180	1181	1182	1183	1184	1185	1186	1187	1188
1189	1190	1191	1192	1193	1194	1195	1196	1197	1198	1199	1200
1201	1202	1203	1204	1205	1206	1207	1208	1209	1210	1211	1212
1213	1214	1215	1216	1217	1218	1219	1220	1221	1222	1223	1224
1225	1226	1227	1228	1229	1230	1231	1232	1233	1234	1235	1236
1237	1238	1239	1240	1241	1242	1243	1244	1245	1246	1247	1248
1249	1250	1251	1252	1253	1254	1255	1256	1257	1258	1259	1260
1261	1262	1263	1264	1265	1266	1267	1268	1269	1270	1271	1272
1273	1274	1275	1276	1277	1278	1279	1280	1281	1282	1283	1284
1285	1286	1287	1288	1289	1290	1291	1292	1293	1294	1295	1296
1297	1298	1299	1300	1301	1302	1303	1304	1305	1306	1307	1308
1309	1310	1311	1312	1313	1314	1315	1316	1317	1318	1319	1320
1321	1322	1323	1324	1325	1326	1327	1328	1329	1330	1331	1332
1333	1334	1335	1336	1337	1338	1339	1340	1341	1342	1343	1344
1345	1346	1347	1348	1349	1350	1351	1352	1353	1354	1355	1356
1357	1358	1359	1360	1361	1362	1363	1364	1365	1366	1367	1368
1369	1370	1371	1372	1373	1374	1375	1376	1377	1378	1379	1380
1381	1382	1383	1384	1385	1386	1387	1388	1389	1390	1391	1392
1393	1394	1395	1396	1397	1398	1399	1400	1401	1402	1403	1404
1405	1406										

CIRCUITO DE ESPERA # HOLDING PATTERN OR	TMA BILBAO									CTA LOGROÑO						CTA PAMPLONA				CTA SAN SEBASTIAN				TMA SANTANDER					CTA VITORIA													
	ASPEB	DVOR/DME BLV 324°	ALBIZ	SUNIR (CONV)	SUNIR (RNAV)	OLUMI	DIRXA	IFASA (CONV)	IFASA (RNAV)	DVOR/DME LPA 072°	DGO (RNAV)	DVOR/DME DGO 110°	VABUS	VABUS (RNAV)	(MPS) NDB EAG 091°	PPN (RNAV)	DVOR/DME PPN R-201 (I)	DVOR/DME PPN R-026 (I)	L PP 356° (I)	DVOR/DME SSN 034°	OSGOT	OSGOT (RNAV)	YESYO	YESYO (RNAV)	SORPO	DVOR/DME SNR 112°	NORAY	NDB SA 111°	NDB SA 291°	RESVA	ARBIN	ARBIN (RNAV)	LOPHA	LOPHA (RNAV)	DVOR/DME VFD 035°	VFD (RNAV)	VOR/DME BUR 218°	BUR (RNAV)				
TMA BILBAO	ASPEB	NC	-	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	-	-	-	FL120	-	-	-	-	-	-	-	-	-	-		
	DVOR/DME BLV 324°	NC	-	NC	NC	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL130	-	-	-	-	-	FL140	FL140	-	-	FL080	FL070	-	-	-			
	ALBIZ	-	NC	-	-	-	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL130	FL130	-	-	-	-			
	SUNIR (CONV)	NC	NC	-	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	-	-	-	-	NC	-	-	-	-	-	-	-	-			
	SUNIR (RNAV)	NC	NC	-	NC	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	-	-	-	-	NC	-	-	-	-	-	-	-	-			
	OLUMI	NC	NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	-	-	-	FL090	-	-	-	-	-	-	-	-			
	DIRXA	-	NC	NC	-	-	-	NC	NC	-	-	-	-	-	-	-	-	-	-	NC	-	-	-	FL090	FL100	-	-	-	-	-	-	FL130	-	-	FL120	FL120	-	-	-			
	IFASA (CONV)	-	NC	NC	-	-	-	NC	-	NC	-	-	-	-	-	-	-	-	-	-	FL130	-	-	-	-	-	-	-	-	-	-	-	FL120	-	-	FL090	FL080	-	-	-		
IFASA (RNAV)	-	NC	NC	-	-	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	FL120	-	-	-	FL140	FL140	-	-	-	-	-	-	-	-	FL140	FL090	-	-	FL080	FL070	-	-	-
CTA LOGROÑO	DVOR/DME LPA 072°	-	-	-	-	-	-	-	-	-	FL070	FL080	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL080	FL080	-	-	FL130	-	-	-	-		
	DGO (RNAV)	-	-	-	-	-	-	-	-	-	FL070	-	NC	NC	NC	FL120	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL070	NC	NC	NC	NC	NC	FL120	FL140	-	-	
	DVOR/DME DGO 110°	-	-	-	-	-	-	-	-	-	FL080	NC	-	NC	NC	FL070	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL110	FL080	NC	NC	FL090	FL090	FL100	FL110	-	-	
	VABUS	-	-	-	-	-	-	-	-	-	NC	NC	NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC	FL100	FL090	-	-	-		
	VABUS (RNAV)	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC	FL080	NC	-	-	-		
	(MPS) NDB EAG 091°	-	-	-	-	-	-	-	-	-	NC	FL120	FL070	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	-	-	-	-	-	-	-		
CTA PAMPLONA	PPN (RNAV)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
	DVOR/DME PPN R-201 (I)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
	DVOR/DME PPN	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	-	NC	FL130	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
	L PP 356° (I)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	-	FL120	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
CTA SAN SEBASTIAN	DVOR/DME SSN 034°	-	-	-	-	-	NC	FL130	FL120	-	-	-	-	-	-	-	-	FL130	FL120	-	FL120	FL100	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
	OSGOT	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL120	-	NC	FL100	FL090	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
	OSGOT (RNAV)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL100	NC	-	FL110	FL090	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
	YESYO	-	-	-	-	-	FL090	-	FL140	-	-	-	-	-	-	-	-	-	-	NC	FL100	FL110	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
TMA SANTANDER	YESYO (RNAV)	-	-	-	-	-	FL100	-	FL140	-	-	-	-	-	-	-	-	-	-	NC	FL090	FL090	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
	SORPO	NC	FL130	-	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	-	NC	NC	NC	NC	-	-	-	-	-	-	-	-		
	DVOR/DME SNR 112°	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	NC	NC	NC	NC	-	-	-	-	-	-	-	-			
	NORAY	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-			
	NDB SA 111°	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC	-	NC	NC	-	-	-	-	-	-	-	-			
CTA VITORIA	NDB SA 291°	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC	-	NC	NC	-	-	-	-	-	-	-	-	-		
	RESVA	FL120	-	-	NC	NC	FL090	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	-	-	-	-	NC	-	-	-	-	-	-	-	-	-		
	ARBIN	-	FL140	-	-	-	-	-	FL140	FL080	FL070	FL110	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	FL110 (I)	NC	NC	NC	NC	-	-	-		
	ARBIN (RNAV)	-	FL140	-	-	-	-	-	FL130	FL120	FL080	FL080	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	FL070	NC	NC	NC	NC	-	-	-		
	LOPHA	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL110 (I)	FL070	-	NC	NC	NC	NC	FL140	FL140	-	-	

NOTE [TMA BILBAO, CTA LOGROÑO, CTA PAMPLONA, CTA SAN SEBASTIÁN, TMA SANTANDER, CTA VITORIA]:
Incompatibility has been considered up to FL145 (inclusive).

1. The holding pattern over DVOR/DME PPN R-202 presents the same incompatibilities as the holding pattern over DVOR/DME PPN R-201.

2. The holding pattern over DVOR/DME PPN R-206 presents the same incompatibilities as the holding pattern over DVOR/DME PPN R-207.

3. The go-around holding pattern over L PP 355° has the same incompatibilities as for IAF L PP 356°.

A speed of 230 kt up to FL140 and 240 kt up to FL145 has been considered.

If a holding speed restriction exists, that condition applies up to FL140.

TMA CANARIAS: ESTE

CIRCUITOS DE ESPERA // HOLDING PATTERN ON			FUERTEVENTURA														LANZAROTE/César Manrique Lanzarote													
			RWY 01							RWY 19							RWY 03					RWY 21								
			NDB FV	SIRPU 04 2° /049°	DURCO 246°	SOTAD (RNAV/RNP)	DURCO RNAV	TENDA 188°	TENDA 245°	TENDA (RNP)	KEMEV	DURCO (RNAV)	KEMEV (RNP)	DURCO 246°	TENDA 236°	TENDA 245°	BAMKU (RNAV/RNP)	MAPED	ROCAZ (RNAV)	DVOR/DME LTE 195°/196°	TICKE (RNAV)	ALEDU (RNAV)	BAPAL (RNAV)	LUNOB	LUNOB (RNAV)	DVOR/DME LTE 028°	INSER (RNAV)	NAVIM (RNAV)	GAKMI (RNAV)	
FUERTEVENTURA	RWY 01	NDB FV		NC	–	7000	–	NC	NC	NC	–	NC	–	NC	NC	6000	–	–	FL230	–	–	FL200	–	–	FL170	–	–	–		
		SIRPU 04 2° /049°	NC		–	NC	–	–	–	–	–	–	FL200	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–		
		DURCO 246°	–	–		–	NC	FL100	–	FL130	–	NC	–	NC	–	–	–	–	NC	–	–	NC	NC	–	–	–	FL110	–	–	
		SOTAD (RNAV/RNP)	7000	NC	–		–	–	–	–	–	–	–	–	–	–	FL170	–	–	–	–	–	–	–	–	–	–	–		
		DURCO RNAV	–	–	NC	–		NC	–	NC	–	NC	–	NC	–	–	–	–	NC	–	–	NC	NC	–	–	–	NC	–	–	
		TENDA 188°	NC	–	FL100	–	NC		NC	NC	NC	NC	FL100	NC	NC	NC	–	–	FL110	–	NC	NC	–	–	NC	–	–	–		
		TENDA 245°	NC	–	–	–	–	NC		NC	FL140	–	FL150	–	NC	NC	NC	–	–	FL130	–	FL170	NC	–	–	NC	–	–	–	
	TENDA (RNP)	NC	–	FL130	–	NC	NC	NC		5000	NC	FL100	FL130	NC	NC	6000	–	–	FL100	–	7000	NC	–	–	NC	–	FL220	–		
	RWY 19	KEMEV	NC	–	–	–	–	NC	FL140	5000		–	NC	–	–	FL140	6000	6000	–	FL210	–	–	–	–	–	FL110	–	–	–	
		DURCO (RNAV)	–	–	NC	–	NC	NC	–	NC	–		–	NC	–	–	–	–	NC	–	–	NC	NC	–	–	–	NC	–	–	
		KEMEV (RNP)	NC	FL200	–	–	–	NC	FL150	FL100	NC	–		–	FL130	FL150	9000	7000	–	FL160	–	–	FL230	–	–	6000	–	–	–	
		DURCO 246°	–	–	NC	–	NC	FL100	–	FL130	–	NC	–		–	–	–	–	NC	–	–	NC	NC	–	–	–	FL110	–	–	
		TENDA 236°	NC	–	–	–	–	NC	NC	NC	–	–	FL130	–		NC	–	–	–	FL130	–	FL150	NC	–	–	NC	–	–	–	
		TENDA 245°	NC	–	–	–	–	NC	NC	NC	FL140	–	FL150	–	NC		NC	–	–	FL130	–	FL170	NC	–	–	NC	–	–	–	
		BAMKU (RNAV/RNP)	6000	–	–	FL170	–	NC	NC	6000	6000	–	9000	–	–	NC		–	–	–	–	–	6000	–	–	FL140	–	–	–	
	LANZAROTE/César Manrique Lanzarote	RWY 03	MAPED	–	–	–	–	–	–	–	6000	–	7000	–	–	–	–		–	FL230	–	–	–	FL190	NC	FL150	–	–	–	
			ROCAZ (RNAV)	–	–	NC	–	NC	–	–	–	–	NC	–	NC	–	–	–		–	–	NC	NC	–	–	–	NC	NC	–	
			DVOR/DME LTE 195°/196°	FL230	–	–	–	–	FL110	FL130	FL100	FL210	–	FL160	–	FL130	FL130	–	FL230	–		–	NC	NC	NC	NC	NC	–	NC	FL190
			TICKE (RNAV)	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–		–	–	–	–	–	NC	FL120	NC	
			ALEDU (RNAV)	–	–	NC	–	NC	NC	FL170	7000	–	NC	–	NC	FL150	FL170	–	–	NC	NC	–		NC	FL160	FL190	NC	NC	NC	–
			BAPAL (RNAV)	FL200	–	NC	–	NC	NC	NC	–	NC	FL230	NC	NC	NC	6000	–	NC	NC	–	NC		–	–	NC	–	–	–	–
		RWY 21	LUNOB	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–	FL190	–	NC	–	FL160	–		NC	FL080	–	FL210	–
			LUNOB (RNAV)	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–	NC	–	NC	–	FL190	–	NC		NC	–	FL170	–
			DVOR/DME LTE 028°	FL170	–	–	–	–	NC	NC	NC	FL110	–	6000	–	NC	NC	FL140	FL150	–	NC	–	NC	NC	FL080	NC		–	NC	–
			INSER (RNAV)	–	–	FL110	–	NC	–	–	–	–	NC	–	FL110	–	–	–	–	NC	–	NC	NC	–	–	–	–		NC	FL110
			NAVIM (RNAV)	–	–	–	–	–	–	–	FL220	–	–	–	–	–	–	–	–	NC	NC	FL120	NC	–	FL210	FL170	NC	NC		FL160
			GAKMI (RNAV)	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–	–	FL190	NC	–	–	–	–	–	FL110	FL160	

AIS-ESPAÑA

AIRAC AMDT 10/26

TMA GALICIA

CIRCUITO DE ESPERA // HOLDING PATTERN ON		A CORUÑA					SANTIAGO												VIGO					
		DVOR/DME LRA 214°	DVOR/DME LRA 217°	MISTE	ENONU	IDOTU	DVOR/DME STG 167°	DVOR/DME STG 347°	ROLFI			NOLMU 348	NOLMU 350	YELTA 319	YELTA 267	LEZUN	OKOVO	REZAK	NDB VON 014°	DVOR/DME VGO 193°	GESPU	BEKIN	OBOTI	PIVON
A CORUÑA	DVOR/DME LRA 214°		NC	NC	NC	NC	FL110	-	-			-	-	-	-	-	6000 ft	NC	-	-	-	-	-	-
	DVOR/DME LRA 217°	NC		NC	NC	NC	FL100	-	-			-	-	-	-	-	6000 ft	NC	-	-	-	-	-	-
	MISTE	NC	NC		NC	-	FL140	-	-			-	-	-	-	-	NC	FL100	-	-	-	-	-	-
	ENONU	NC	NC	NC		-	-	-	-			-	-	-	-	-	-	FL110	-	-	-	-	-	-
	IDOTU	NC	NC	-	-		FL070	-	-			-	-	-	-	6000 ft	-	NC	-	-	-	-	-	-
SANTIAGO																								
	DVOR/DME STG 167°	FL110	FL100	FL140	-	FL070		NC	NC			FL100	NC	5000 ft	NC	NC	NC	NC	-	FL140	-	-	-	6000 ft
	DVOR/DME STG 347°	-	-	-	-	-	NC		NC			NC	NC	NC	NC	NC	NC	NC	-	FL110	-	FL140	-	NC
	ROLFI	-	-	-	-	-	NC	NC				NC	NC	NC	NC	NC	-	-	-	NC	-	NC	-	NC
	NOLMU 348	-	-	-	-	-	FL100	NC	NC				NC	NC	NC	-	-	-	FL140	NC	-	NC	FL120	NC
	NOLMU 350	-	-	-	-	-	NC	NC	NC			NC		NC	NC	-	-	-	FL140	NC	-	NC	6000 ft	NC
	YELTA 319	-	-	-	-	-	5000 ft	NC	NC			NC	NC		NC	-	FL080	-	-	FL140	-	-	-	NC
	YELTA 267	-	-	-	-	-	NC	NC	NC			NC	NC	NC		FL140	5000 ft	-	-	FL140	-	-	-	NC
	LEZUN	-	-	-	-	6000 ft	NC	NC	NC			-	-	-	FL140		NC	NC	-	-	-	FL140	-	FL110
	OKOVO	6000 ft	6000 ft	NC	-	-	NC	NC	-			-	-	FL080 ft	5000 ft	NC		NC	-	-	-	-	-	FL140
VIGO	REZAK	NC	NC	FL100	FL110	NC	NC	NC	-			-	-	-	-	NC	NC		-	-	-	-	-	-
	NDB VON 014°	-	-	-	-	-	-	-	-			FL140	FL140	-	-	-	-	-		NC	NC	NC	NC	FL070
	DVOR/DME VGO 193°	-	-	-	-	-	FL140	FL110	NC			NC	NC	FL140	FL140	-	-	-	NC		6000 ft	NC	NC	NC
	GESPU	-	-	-	-	-	-	-	-			-	-	-	-	-	-	-	NC	6000 ft		FL140	NC	-
	BEKIN	-	-	-	-	-	-	FL140	NC			NC	NC	-	-	FL140	-	-	NC	NC	FL140		8000 ft	NC
	OBOTI	-	-	-	-	-	-	-	-			FL120	6000 ft	-	-	-	-	-	NC	NC	NC	8000 ft		FL070
	PIVON	-	-	-	-	-	6000 ft	NC	NC			NC	NC	NC	NC	FL110	FL140	-	FL070	NC	-	NC	FL070	

NOTE [TMA GALICIA]:

- Two holding patterns are considered incompatible at a given altitude when the separation between their basic protected areas is less than 5 NM.
- The altitudes used for the study are expressed in thousands of feet up to the transition altitude, above which flight levels are used. The transition altitude from which flight levels are applied is 6,000 ft.
- The compatibility study has been conducted starting from the most restrictive minimum altitude/flight level for each pair of holding patterns.
- Incompatibility has been assessed up to and including FL150.
- Holding patterns with an RNAV 1 specification have been assessed using GNSS as the navigation sensor up to and including FL080, and DME/DME above that altitude.
- Where both RNAV and conventional holding patterns exist at the same waypoint with identical parameters, the more restrictive one has been considered.

MADRID TMA: CONFIGURACIÓN SUR // SOUTH CONFIGURATION

CIRCUITO DE ESPERA // HOLDING PATTERN ON	NONTU	ORBIS RNAV	ORBIS (CONV.) (STAR LETO)	PODOG	RILKO	SIE DVOR/DME CONV.	USATI	SECOO	NVS RNAV	NVS DVOR/DME CONV. (STAR LETO)	TLD RNAV	TLD DVOR/DME CONV. (STAR LETO)	BUREX CONV. (STAR LETO)	LULER	VENUX	BAN	NOSKO RNAV	NOSKO CONV. (STAR-LETO)	CJN RNAV	CJN DVOR/DME CONV. (324 ° -144 °) (STAR LEGT)	CJN DVOR/DME CONV. (240 ° -060 °) (STAR LEGT)	ADUXO	PRADO	TERSA	SIRGU CONV. (STAR LETO)	DUKKE CONV. (STAR LETO)	VTB DVOR/DME CONV. (STAR LEGT)	GE NDB CONV. (STAR LEGT)	ROFIX FRUSTRADA IAC LEMD RWY 18L/R
NONTU		NC	NC	NC	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
ORBIS RNAV	NC		NC	NC	NC	12000	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
ORBIS CONV. (STAR LETO)	NC	NC		NC	-	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
PODOG	NC	NC	NC		-	FL200	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
RILKO	-	NC	-	-		NC	-	-	-	-	-	-	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
SIE DVOR/DME CONV.	NC	12000	NC	FL200	NC		-	-	-	-	-	-	-	NC	FL190	-	-	-	-	-	-	-	-	-	-	-	-	-	
USATI	-	NC	NC	NC	-	-		NC	-	FL200	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
SECOO	-	-	-	-	-	-	NC		NC	NC	-	FL170	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL190	
NVS RNAV	-	-	-	-	-	-	-	NC		NC	NC	NC	FL150	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	
NVS DVOR/DME CONV. (STAR LETO)	-	-	-	-	-	-	FL200	NC	NC		NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	10000	
TLD RNAV	-	-	-	-	-	-	-	-	NC	NC		NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	
TLD DVOR/DME CONV. (STAR-LETO)	-	-	-	-	-	-	-	FL170	NC	NC	NC		NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	12000	
BUREX CONV. (STAR-LETO)	-	-	-	-	-	-	-	-	FL150	-	NC	NC		-	-	-	-	-	-	-	-	-	-	-	-	-	-	9000	10000
LULER	-	-	-	-	NC	NC	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-	-	-	-	
VENUX	-	-	-	-	-	FL190	-	-	-	-	-	-	-	-		NC	FL200	FL150	-	-	-	-	-	-	-	-	-	-	
BAN	-	-	-	-	-	-	-	-	-	-	-	-	-	NC		-	FL220	-	-	-	-	-	-	-	-	-	-	-	
NOSKO RNAV	-	-	-	-	-	-	-	-	-	-	-	-	-	FL200	-		NC	NC	NC	NC	NC	NC	FL200	NC	NC	NC	-	-	
NOSKO CONV. (STAR-LETO)	-	-	-	-	-	-	-	-	-	-	-	-	-	FL150	FL220	NC		NC	NC	NC	NC	FL180	-	NC	FL180	NC	-	-	
CJN RNAV	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC		NC	NC	NC	NC	FL200	NC	NC	-	-	
CJN DVOR/DME CONV. (324 ° -144 °) (STAR-LEGT)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC		NC	NC	NC	FL170	NC	NC	-	-	
CJN DVOR/DME CONV. (240 ° -060 °) (STAR-LEGT)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC		NC	NC	NC	-	NC	-	-	
ADUXO	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	FL180	NC	NC	NC		NC	NC	NC	FL200	-	-	
PRADO	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL200	-	NC	NC	NC	NC		-	NC	-	-	-	
TERSA	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	FL200	FL170	NC	NC	-		FL180	FL190	-	-	
SIRGU CONV. (STAR LETO)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	FL180	NC	NC	-	NC	NC	FL180		FL140	-	-	
DUKKE CONV. (STAR LETO)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC	NC	NC	FL200	-	FL190	FL140		-	-	
VTB DVOR/DME CONV. (STAR LEGT)	-	-	-	-	-	-	-	-	-	-	-	-	9000	-	-	-	-	-	-	-	-	-	-	-	-	-	-	FL200	
GE NDB CONV. (STAR LEGT)	-	-	-	-	-	-	-	FL190	NC	10000	NC	12000	10000	-	-	-	-	-	-	-	-	-	-	-	-	-	FL200		NC
ROFIX FRUSTRADA IAC LEMD RWY 18L/R	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	

NOTA // NOTE [MADRID TMA: CONFIGURACIÓN SUR // SOUTH CONFIGURATION]:

De manera general, en los puntos donde existen definidas diferentes esperas para esta configuración del TMA, los valores corresponden a la interacción más restrictiva. Adicionalmente, en algunos casos particulares se incluye información segregada para diferentes esperas en un mismo punto. // As a general rule, for the points where different holdings are defined for this TMA configuration, the figures correspond to the most restrictive interaction. In addition, in specific cases segregated information on different holdings for the same point is provided.

MADRID TMA: CONFIGURACIÓN NORTE // NORTH CONFIGURATION

CIRCUITO DE ESPERA HOLDING PATTERN ON	BUREX	TLD	DAQSE	AVILA	ORBIS	FAFEQ	SIRGU	ADUXO	TERSA	PRADO	NOSKO	BAN	RUDBI	VTB DVOR/DME CONV. (STAR LEGT)	CJN DVOR/DME CONV. (324 ° -144 °) (STAR LEGT)	CJN DVOR/DME CONV. (240 ° -60 °) (STAR LEGT)	NVS DVOR/DME CONV. (STAR LETO)	TOBEK CONV. (STAR LETO)	ASBIN CONV. (STAR LETO)	GE NDB (STAR LEGT)	DUKKE CONV. (STAR LETO)	ROFIX FRUSTRADA IAC LEMD RWY 32L/R	PDT DVOR/DME CONV.
BUREX		NC	FL190	-	-	-	-	-	-	-	-	-	-	NC	-		-	-	-	-	-	-	-
TLD	NC		NC	FL200	-	-	-	-	-	-	-	-	-	-	-		NC	-	-	-	-	-	-
DAQSE	FL190	NC		NC	-	-	-	-	-	-	-	-	-	-	-		NC	-	-	-	-	-	-
AVILA	-	FL200	NC		FL210	-	-	-	-	-	-	-	-	-	-		NC	-	-	-	-	-	-
ORBIS	-	-	-	FL210		-	-	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-
FAFEQ	-	-	-	-	-		-	-	-	-	-	-	NC	-	-		-	NC	NC	-	-	NC	NC
SIRGU	-	-	-	-	-	-		NC	FL180	NC	FL160	-	NC	-	NC		-	-	NC	-	NC	-	-
ADUXO	-	-	-	-	-	-	NC		NC	NC	FL170	-	-	-	NC		-	-	-	-	FL190	-	-
TERSA	-	-	-	-	-	-	FL180	NC		-	NC	-	-	-	FL200		-	-	-	-	FL190	-	-
PRADO	-	-	-	-	-	-	NC	NC	-		-	-	-	-	NC		-	-	-	-	-	-	-
NOSKO	-	-	-	-	-	-	FL160	FL170	NC	-		FL190	12000	-	NC		-	-	-	-	NC	-	-
BAN	-	-	-	-	-	-	-	-	-	-	FL190		-	-	-		-	-	-	-	FL200	-	-
RUDBI	-	-	-	-	-	NC	NC	-	-	-	12000	-		-	NC		-	NC	NC	-	NC	-	NC
VTB DVOR/DME CONV. (STAR LEGT)	NC	-	-	-	-	-	-	-	-	-	-	-	-		-		-	-	-	-	-	-	-
CJN DVOR/DME CONV. (324 ° -144 °) (STAR LEGT)	-	-	-	-	-	-	NC	NC	FL200	NC	NC	-	NC	-			-	-	-	-	NC	-	-
CJN DVOR/DME CONV. (240 ° -60 °) (STAR LEGT)	-	-	-	-	-	-	-	NC	NC	NC	NC	-	NC	-	NC		-	-	-	-	NC	-	-
NVS DVOR/DME CONV. (STAR LETO)	-	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-
TOBEK CONV. (STAR LETO)	-	-	-	-	-	NC	-	-	-	-	-	-	NC	-	-		-		NC	-	-	NC	NC
ASBIN CONV. (STAR LETO)	-	-	-	-	-	NC	NC	-	-	-	-	-	NC	-	-		-	NC		-	-	-	NC
GE NDB (STAR LEGT)	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-		NC	NC	-	-	-	NC	-
DUKKE CONV. (STAR LETO)	-	-	-	-	-	-	NC	FL190	FL190	-	NC	FL220	NC	-	NC		-	-	-	-		-	-
ROFIX FRUSTRADA IAC LEMD RWY 32L/R	-	-	-	-	-	NC	-	-	-	-	-	-	-	-	-		-	NC	-	-	-		-
PDT DVOR/DME CONV.	-	-	-	-	-	NC	-	-	-	-	-	-	NC	-	-		-	NC	NC	-	-	-	

NOTA // NOTE [MADRID TMA: CONFIGURACIÓN NORTE // NORTH CONFIGURATION]:

De manera general, en los puntos donde existen definidas diferentes esperas para esta configuración del TMA, los valores corresponden a la interacción más restrictiva. Adicionalmente, en algunos casos particulares se incluye información segregada para diferentes esperas en un mismo punto. // As a general rule, for the points where different holdings are defined for this TMA configuration, the figures correspond to the most restrictive interaction. In addition, in specific cases segregated information on different holdings for the same point is provided.

MURCIA/AEROPUERTO DE LA REGIÓN DE MURCIA

CIRCUITOS DE ESPERA // HOLDING PATTERN ON			MURCIA/Aeropuerto de la Región de Murcia					MURCIA/San Javier							ALICANTE/Alicante-Elche Miguel Hernández						
			RWY 05/23					RWY 04R/22L							RWY 10			RWY 28			
			VOR/DME ALT FL130 279°	DITRE FL090 234°	SANSI 4500 ft 353°	NERKU 5500 ft 037°	RWY 04R SANSI 3500 ft 035°	RWY 04R/22L VOR/TACAN VSJ 2400 ft 217°	(MIPS) RWY 22L VOR/TACAN VSJ 3000 ft 063°	(MIPS) RWY 04R 3500 ft R- 225 /15.0 DME VSJ	RWY 04R/22L PALOS 4000 ft 312°	RWY 22L DITRE 4000 ft 233°	(MIPS) RWY 22L FL170 R- 266 /5.0 DME VSJ	(MIPS) RWY 22L VOR/TACAN VSJ 3000 ft 046°	VILNA FL070 144°	MAGAL FL070 (4000 ft ATC & MA) 305°	VOR/DME ALT 4000 ft 278°	BESOR 6500 ft 237°	VOR/DME ALT 4500 ft 100°	MAGAL STAR & MA 4000 ft 307°	DVOR/DME VLC FL080 R-168/370 DME VLC
MURCIA/Aeropuerto de la Región de Murcia	RWY 05/23	VOR/DME ALT FL130 279°		NC	–	–	–	NC	FL200	–	–	NC	FL240	FL190	FL140	NC	NC	NC	NC	NC	–
		DITRE FL090 234°	NC		–	–	–	NC	NC	–	FL110	NC	FL210	NC	–	NC	NC	–	NC	NC	–
		SANSI 4500 ft 353°	–	–		FL130	NC	FL100	NC	NC	FL210	–	NC	NC	–	–	–	–	–	–	–
		NERKU 5500 ft 037°	–	–	FL130		FL130	–	FL190	FL130	–	–	FL220	FL190	–	–	–	–	–	–	–
MURCIA/San Javier	RWY 04R/22L	RWY 04R SANSI 3500 ft 035°	–	–	NC	FL130		FL140	3500	NC	–	–	NC	NC	–	–	–	–	–	–	–
		RWY 04R/22L VOR/TACAN VSJ 2400 ft 217°	NC	NC	FL100	–	FL140		NC	NC	FL090	NC	NC	NC	–	FL150	FL120	–	FL120	FL150	–
		(MIPS) RWY 22L VOR/TACAN VSJ 3000 ft 063°	FL200	NC	NC	FL190	3500	NC		NC	FL130	NC	NC	NC	–	–	FL200	–	FL190	–	–
		(MIPS) RWY 04R 3500 ft R- 225 /15.0 DME VSJ	–	–	NC	FL130	NC	NC	NC		–	–	NC	NC	–	–	–	–	–	–	–
		RWY 04R/22L PALOS 4000 ft 312°	–	FL110	FL210	–	–	FL090	FL130	–		FL110	–	FL120	–	–	–	–	–	–	–
		RWY 22L DITRE 4000 ft 233°	NC	NC	–	–	–	NC	NC	–	FL110		FL210	NC	–	NC	5000	–	NC	NC	–
		(MIPS) RWY 22L FL170 R- 266 /5.0 DME VSJ	FL240	FL210	NC	FL220	NC	NC	NC	NC	–	FL210		NC	–	–	FL200	–	FL190	–	–
		(MIPS) RWY 22L VOR/TACAN VSJ 3000 ft 046°	FL190	NC	NC	FL190	NC	NC	NC	NC	FL120	NC	NC		–	–	FL200	–	FL190	–	–
ALICANTE/Alicante- Elche Miguel Hernández	RWY 10	VILNA FL070 144°	FL140	–	–	–	–	–	–	–	–	–	–		–	NC	–	FL140	–	FL200	
		MAGAL FL070 (4000 ft ATC & MA) 305°	NC	NC	–	–	–	FL150	–	–	–	NC	–	–	–		FL140	FL140	NC	NC	–
		VOR/DME ALT 4000 ft 278°	NC	NC	–	–	–	FL120	FL200	–	–	5000	FL200	FL200	NC	FL140		FL140	NC	FL140	–
	RWY 28	BESOR 6500 ft 237°	NC	–	–	–	–	–	–	–	–	–	–	–	–	FL140	FL140		NC	FL140	FL200
		VOR/DME ALT 4500 ft 100°	NC	NC	–	–	–	FL120	FL190	–	–	NC	FL190	FL190	FL140	NC	NC	NC		NC	–
		MAGAL STAR & MA 4000 ft 307°	NC	NC	–	–	–	FL150	–	–	–	NC	–	–	–	NC	FL140	FL140	NC		–
		DVOR/DME VLC FL080 R-168/370 DME VLC	–	–	–	–	–	–	–	–	–	–	–	–	FL200	–	–	FL200	–	–	

NOTA // NOTE [MURCIA/Aeropuerto de la Región de Murcia]:



La incompatibilidad se ha considerado hasta FL240 (inclusive). // Incompatibility has been considered up to FL240 (inclusive).

En los recuadros se indica el nivel de vuelo o altitud superior en el que ambas esperas son aún compatibles. // The highest flight level or altitude on which both holding patterns are still compatible is indicated in the boxes.

Los recuadros en blanco indican que no se produce incompatibilidad hasta el nivel de vuelo considerado. // Empty boxes indicate that incompatibility does not occur up to the flight level considered.

Los rumbos en las esperas son de acercamiento. // Headings in holding patterns are inbound.

En el caso que existan esperas RNAV y convencionales, se ha considerado la más restrictiva entre las dos. // If there are RNAV and conventional holding patterns, it is considered the most restricted holding pattern of both.

NC: No compatibles. // NC: Not compatible.

MA: Aproximación frustrada. // MA: Missed approach.



PALMA TMA

CIRCUITOS DE ESPERA // HOLDING PATTERN ON		PALMA DE MALLORCA													IBIZA										MENORCA						
		NDB ADX 123°	DVOR/ DME POS 150°	DVOR/ DME CDP 273°	POSBA	RUPIT	MUROS	DVOR/ DME MUJ 052°	DVOR/ DME MUJ 261°	TAKUS	INPUS	BAVUM	IBIVU	TUTOT	DEMEV	NELUX	NEGRE	KOXES	VOR/DME IBA 243°	SISDU	OLPAM	VOR/DME IBA 063°	XEMDU	GISLU	NDB IZA 242°	DONAV	DVOR/ DME MHN 189°	DVOR/ DME MHN 007°	DVOR/ DME MHN 005°	BALIO	NDB MN 007°
PALMA DE MALLORCA	NDB ADX 123°		-	-	-	NC	-	NC	6000	FL150	FL220	-	FL200	-	-	FL220	FL140	-	-	-	-	-	-	FL210	-	-	-	-	-	-	-
	DVOR/DME POS 150°	-		FL100	NC	-	NC	FL200	FL160	NC	NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
	DVOR/DME CDP 273°	-	FL100		-	-	NC	FL230	FL140	FL080	-	NC	-	-	-	-	-	-	-	-	-	-	-	-	FL220	FL150	FL140	FL140	FL150	FL140	
	POSBA	-	NC	-		-	FL220	-	-	FL120	NC	FL200	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
	RUPIT	NC	-	-	-		-	FL150	-	-	-	-	FL220	FL210	-	FL170	NC	-	FL170	-	FL180	-	-	5000	FL150	-	-	-	-	-	
	MUROS	-	NC	NC	FL220	-		FL150	5000	NC	FL220	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
	DVOR/DME MUJ 052°	NC	FL200	FL230	-	FL150	FL150		NC	NC	-	FL140	NC	-	-	FL160	FL170	-	-	-	-	-	-	FL180	FL220	-	-	-	-	-	
	DVOR/DME MUJ 261°	6000	FL160	FL140	-	-	5000	NC		NC	-	NC	FL080	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
	TAKUS	FL150	NC	FL080	FL120	-	NC	NC	NC		NC	NC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
	INPUS	FL220	NC	-	NC	-	FL220	-	-	NC		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
	BAVUM	-	NC	NC	FL200	-	NC	FL140	NC	NC	-		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
	IBIVU	FL200	-	-	-	FL220	-	NC	FL080	-	-	-		-	-	4000	FL140	-	-	-	-	-	-	FL140	FL190	-	-	-	-	-	-
IBIZA	TUTOT	-	-	-	-	FL210	-	-	-	-	-	-		NC	FL190	FL140	NC	NC	NC	NC	NC	NC	FL110	NC	-	-	-	-	-	-	
	DEMEV	-	-	-	-	-	-	-	-	-	-	-	NC		-	-	NC	-	NC	-	NC	-	-	-	-	-	-	-	-	-	
	NELUX	FL220	-	-	-	FL170	-	FL160	-	-	-	4000	FL190	-		FL070	FL140	FL090	-	FL190	FL190	NC	NC	NC	-	-	-	-	-	-	
	NEGRE	FL140	-	-	-	NC	-	FL170	-	-	-	FL140	FL140	-	FL070		FL190	FL090	-	NC	FL190	FL200	NC	NC	-	-	-	-	-	-	
	KOXES	-	-	-	-	-	-	-	-	-	-	-	NC	NC	FL140	FL190		NC	FL090	NC	NC	NC	FL130	NC	-	-	-	-	-	-	
	VOR/DME IBA 243°	-	-	-	-	FL170	-	-	-	-	-	-	NC	-	FL090	FL090	NC		FL090	NC	NC	NC	NC	NC	-	-	-	-	-	-	
	SISDU	-	-	-	-	-	-	-	-	-	-	NC	NC	-	-	FL090	FL090		5000	NC	-	-	-	-	-	-	-	-	-	-	
	OLPAM	-	-	-	-	FL180	-	-	-	-	-	-	NC	-	FL190	NC	NC	NC	5000		NC	NC	NC	NC	-	-	-	-	-	-	
	VOR/DME IBA 063°	-	-	-	-	-	-	-	-	-	-	-	NC	NC	FL190	FL190	NC	NC	NC	NC		NC	FL100	NC	-	-	-	-	-	-	
	XEMDU	-	-	-	-	-	-	-	-	-	-	-	NC	-	NC	FL200	NC	NC	-	NC	NC		NC	NC	-	-	-	-	-	-	
	GISLU	FL210	-	-	-	5000	-	FL180	-	-	-	-	FL140	FL110	-	NC	NC	FL130	NC	-	NC	FL100	NC		NC	-	-	-	-	-	-
	MENORCA	NDB IZA 242°	-	-	-	-	FL150	-	FL220	-	-	-	-	FL190	NC	-	NC	NC	NC	NC	-	NC	NC	NC		-	-	-	-	-	-
DONAV		-	-	FL220	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		NC	NC	NC	-	3000	
DVOR/DME MHN 189°		-	-	FL150	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC		NC	NC	NC	NC	
DVOR/DME MHN 007°		-	-	FL140	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC		NC	NC	NC	
DVOR/DME MHN 005°		-	-	FL140	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC		NC	NC	
BALIO		-	-	FL150	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	NC	NC	NC		NC	
	NDB MN 007°	-	-	FL140	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3000	NC	NC	NC	NC		

NOTA // NOTE [PALMA TMA]:

La incompatibilidad se ha considerado hasta FL240 (inclusive). // Incompatibility has been considered up to FL240 (inclusive).

En los recuadros se indica el nivel de vuelo o altitud superior en el que ambas esperas son aún compatibles. // The highest flight level or altitude on which both holding patterns are still compatible is indicated in the boxes.

Los recuadros en blanco indican que no se produce incompatibilidad hasta el nivel de vuelo considerado. // Empty boxes indicate that incompatibility does not occur up to the flight level considered.

Los rumbos en las esperas son de acercamiento. // Headings in holding patterns are inbound.

En el caso que existan esperas RNAV y convencionales, se ha considerado la más restrictiva entre las dos. // If there are RNAV and conventional holding patterns, it is considered the most restricted holding pattern of both.

NC: No compatibles. // NC: Not compatible.

[illegible]

TMA VALENCIA

CIRCUITO DE ESPERA // HOLDING PATTERN ON			ALICANTE										CASTELLÓN					VALENCIA									
			RWY10			RWY28							RWY06				RWY24	RWY12					RWY30				
			VILNA	VOR/DME ALT (278°)	MAGAL (305°)	MAGAL (307°)	MAGAL RNAV	VOR/DME ALT (100°)	BESOR	BESOR RNAV	DVOR/DME VLC 370 DME R-168	SAURA	NIBEN	IQOEP	DVOR/DME CTN	OSPES	OPERA	DVOR/DME CLS	URIAS	DVOR/DME VLC (118°)	DVOR/DME VLC (298°)	DVOR/DME VLC (118°)	MULAT	NDB SGO			
ALICANTE	RWY10	VILNA		FL120	-	-	-	NC	-	-	FL200	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
		VOR/DME ALT (278°)	FL120		NC	NC	NC	NC	NC	NC	-	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
		MAGAL (305°)	-	NC		NC	NC	FL110	FL100	FL100	-	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
	RWY28	MAGAL (307°)	-	NC	NC		NC	FL100	FL100	FL100	-	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
		MAGAL RNAV	-	NC	NC	NC		NC	FL100	FL100	-	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
		VOR/DME ALT (100°)	NC	NC	FL110	FL100	NC		FL120	NC	-	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
		BESOR	-	NC	FL100	FL100	FL100	FL120		NC	FL200	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
		BESOR RNAV	-	NC	FL100	FL100	FL100	NC	NC		FL180	-	-	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
		DVOR/DME VLC 370 DME R-168	FL200	-	-	-	-	-	FL200	FL180		-	-	INFO NO AVBL		-	-	-	NC	FL200	FL140	FL200	FL150	-			
	CASTELLÓN	RWY06	SAURA	-	-	-	-	-	-	-	-		NC	INFO NO AVBL		-	-	-	-	-	-	-	-	-			
NIBEN			-	-	-	-	-	-	-	-	-	NC		INFO NO AVBL		-	-	-	-	-	-	-	NC				
IQOEP			INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL	INFO NO AVBL			
DVOR/DME CTN			-	-	-	-	-	-	-	-	-	NC	-	INFO NO AVBL		NC	-	-	-	-	-	-	FL140				
RWY24		OSPES	-	-	-	-	-	-	-	-	-	-	INFO NO AVBL			-	-	-	-	-	-	-	-				
VALENCIA	RWY12	OPERA	-	-	-	-	-	-	-	-	-	-	INFO NO AVBL		-		NC	-	NC	NC	NC	-	FL190				
		DVOR/DME CLS	-	-	-	-	-	-	-	-	-	-	INFO NO AVBL		-	NC		-	NC	FL180	NC	-	-				
		URIAS	-	-	-	-	-	-	-	-	NC	-	-	INFO NO AVBL		-	-		NC	NC	NC	NC	-				
		DVOR/DME VLC (118°)	-	-	-	-	-	-	-	-	FL200	-	-	INFO NO AVBL		-	NC	NC	NC		NC	NC	NC	NC			
		DVOR/DME VLC (298°)	-	-	-	-	-	-	-	-	FL140	-	-	INFO NO AVBL		-	NC	FL180	NC	NC		NC	NC	NC			
	RWY30	DVOR/DME VLC (118°)	-	-	-	-	-	-	-	-	FL200	-	-	INFO NO AVBL		-	NC	NC	NC	NC	NC		NC	NC			
		MULAT	-	-	-	-	-	-	-	-	FL150	-	-	INFO NO AVBL		-	-	-	NC	NC	NC	NC		NC			
		NDB SGO	-	-	-	-	-	-	-	-	-	-	NC	INFO NO AVBL		-	FL190	-	-	NC	NC	NC	NC				



4.2. PROCEDURES AT AFIS AERODROMES

GENERAL

The AFIS unit shall issue information to aircraft in its area of responsibility to achieve a safe, orderly and expeditious flow of air traffic. AFIS officers (AFISO) shall maintain a continuous watch by visual observation of all flight operations on and in the vicinity of an aerodrome, as well as vehicles and personnel on the manoeuvring area.

An Apron Management Service is provided by AFIS to regulate the activities and movement of aircraft on the apron.

Aircraft at AFIS aerodromes and within their associated FIZ shall operate in accordance with a flight plan and must be equipped for two way radio communications.

The pilot shall establish and maintain two way communications with the AFIS unit, and he/she shall notify his position, altitude, and any significant manoeuvres and intentions to this unit.

In general, the pilot shall provide all information requested by the AFIS unit for the fulfillment of its duties.

Whilst operating at the airport or in its vicinity, the pilot shall, based on the information provided by the AFIS unit and his/her own knowledge and observations, decide on the actions to take in order to ensure its separation from aircraft, land vehicles and obstacles.

AFIS shall stick to duly report essential traffic information, with which the pilot shall decide on the appropriate trajectory or manoeuvre to follow. Regardless of any pilot action, the

AFIS officer shall report, adequately and without delay, information with regard to any perceived dangerous situation in his area of responsibility.

Flight plans shall be submitted according to ENR 1.10, nevertheless, where an AFIS aerodrome has no associated air traffic reporting office, flight plans may be submitted or closed by means of a report to the AFIS unit of the aerodrome. The service provided by the AFIS unit in that case is comparable to that of an air traffic reporting office.

OPERATIONS IN THE FLIGHT INFORMATION ZONE

ARRIVALS

IFR traffic bound for an AFIS aerodrome, shall contact with the AFIS unit, notify their intentions and enter the FIZ following the procedures established in the approach charts.

VFR traffic bound for an AFIS aerodrome, shall contact the AFIS unit and notify their intentions prior to reaching the reporting points indicated in the Visual Approach Chart.

VFR traffic shall enter the FIZ via the designated points, proceeding on the indicated magnetic tracks to join the visual circuit maintaining the maximum altitude published in the Visual Approach Chart.

As soon as possible, after the aircraft have established contact with the AFIS unit and before the aircraft joins the traffic circuit, the following information shall be provided, except that known to have been already received by the pilot:

- a. the preferential runway and direction of the traffic circuit;
- b. up to date meteorological information; and
- c. essential traffic information and aerodrome conditions, when appropriate.

The AFIS officer shall not provide any instructions with regard to joining the traffic circuit, nor shall he/she establish a landing order.

The pilot will report joining the circuit, on base and on final.

Once the landing has been completed, the pilot shall report his/her taxi intentions, he/she shall request permission to enter the apron and he/she shall notify when the flight plan has been terminated.

As soon as possible aircraft shall report missed approaches and their intentions, if it is the case.

DEPARTURES

IFR traffic departing from an AFIS aerodrome shall contact with the AFIS unit and notify their intentions. Before take-off, the AFIS unit shall relay the appropriate ATC clearance (CTOT included when subject to ATFM measures) provided to enter in controlled airspace, the traffic information and the assigned transponder code.

VFR traffic intending to leave the FIZ, shall do so via the designated points and they shall notify their intentions to the AFIS unit,



including the reporting point to be used.

The VFR flight shall report the AFIS leaving the FIZ over the relevant reporting point.

COMMUNICATIONS FAILURE

The communications failure procedure is detailed in the Visual Approach Chart.