

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA

Dirección AFTN: LEANZXTA

Teléfono: +34 913 213 363

E-mail: ais@enaire.es

Web: www.enaire.es

ENAIRE

DIVISIÓN DE INFORMACIÓN AERONÁUTICA

c/ Campezo, 1. EDIFICIO 2

Kudos Innovation Campus Las Mercedes

28022 Madrid (ESPAÑA)

SUP 75/24

AIRAC 02-MAY-24

EFFECTIVE DATE WEF 13-JUN-24

AD

SUP 75/24

13JUN24/13JUN 25EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

GIRONA AD (LEGE).- Works to replace ILS/DME RWY 19 "IGN"

Until 13 June 2025 (estimated), updates related to the replacement of the ILS/DME RWY 19 "IGN" system will be underway.

The works will be conducted in three phases. The works described for each phase and zone will not necessarily be executed simultaneously, rather they will be scheduled based on the operations affected.

The start and end dates of each phase, as well as any operational incidents that may arise, will be announced via the corresponding NOTAM.

All work areas will be duly marked and lit.

PHASE 1: Preliminary stockpiling and stakeout

No operational impact on ILS.

PHASE 2: Disconnection of GP/DME RWY 19

The actions will be performed with GP/DME RWY 19 out of service.

These tasks will require workers and machinery to be present in the zone and in the critical area of GP/DME RWY 19.

The following instrument approach procedures will not be usable (U/S):

– IAC/4 - ILS Z RWY 19.

– IAC/5 - ILS Y RWY 19.

Other procedures will be operational.

PHASE 3: Disconnection of ILS/DME RWY 19

The actions shall be performed with the ILS/DME RWY 19 (LOC and GP/DME RWY 19) system completely out of service.

These tasks will require workers and machinery to be present in the zone and in the critical area of GP/DME RWY 19 and LOC RWY 19.

The following instrument approach procedures will not be usable (U/S):

– IAC/4 - ILS Z RWY 19.

– IAC/5 - ILS Y RWY 19.

– IAC/6 - LOC Z RWY 19.

– IAC/7 - LOC Y RWY 19.

Other procedures will be operational.

SUP 75/24