

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA

Dirección AFTN: LEANZXTA

Teléfono: +34 913 213 363

E-mail: ais@enaire.es

Web: www.enaire.es

ENAIRE

DIVISIÓN DE INFORMACIÓN AERONÁUTICA

c/ Campezo, 1. EDIFICIO 2

Kudos Innovation Campus Las Mercedes

28022 Madrid (ESPAÑA)

SUP 175/25

AIRAC 18-SEP-25

EFFECTIVE DATE WEF 30-OCT-25

AD

SUP 175/25

30OCT25/30OCT26EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

PALMA DE MALLORCA (LEPA/LESJ).- Scheduled withdrawal of DVOR/DME POS of Pollensa.

Until 30 October 2026 (estimated), actions related to the replacement of DVOR/DME POS will be carried out, and the system will be out of service.

Afected procedure / segment:

- STAR 3 RWY 24L/24R:
 - LORES1P radar assistance.
 - TOLSO2P radar assistance between segment LISAS-POS.

The following procedures / segments will be unavailable (U/S), although the connecting points of the SIDs and STARs are still plannable:

Palma de Mallorca airport:

- SID 1 RWY 06L: DRAGO3L, EPAMA2L, GALAT3L.
- SID 2 RWY 06R: DRAGO4B, EPAMA3B, GALAT4B.
- STAR 1 RWY 06L/R: LORES3M.
- STAR 3 RWY 24L/24R: holding over DVOR/DME POS and holding over POSBA.
- IAC/7 ILS Z RWY 24L: initial segment and holding over DVOR/DME POS.
- IAC/8 ILS Y RWY 24L: initial segment and holding over DVOR/DME POS.
- IAC/9 LOC RWY 24L: initial segment and holding over DVOR/DME POS.
- IAC/10 NDB RWY 24L: initial segment and holding over DVOR/DME POS.
- IAC/13 ILS Z RWY 24R: initial segment and holding over DVOR/DME POS.
- IAC/14 ILS Y RWY 24R: initial segment and holding over DVOR/DME POS.
- IAC/15 LOC RWY 24R: initial segment and holding over DVOR/DME POS.

- IAC/16 VOR RWY 24R: initial segment and holding over DVOR/DME POS.

The remaining procedures will be operational.

- SUP 175/25 -