

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA

Dirección AFTN: LEANZXTA

Teléfono: +34 913 213 363

E-mail: ais@enaire.es

Web: www.enaire.es

ENAIRE

DIVISIÓN DE INFORMACIÓN AERONÁUTICA

c/ Campezo, 1. EDIFICIO 2

Kudos Innovation Campus Las Mercedes

28022 Madrid (ESPAÑA)

SUP 27/25

AIRAC 06-FEB-25

EFFECTIVE DATE WEF 20-MAR-25

AD

SUP 27/25

20MAR25/20MAR26EST

NOTE: EST SUP will only be cancelled by NOTAM, SUP or AIP amendment.

MENORCA AD (LEMH).- Renovation of the engine generator control system.

Until 20 March 2026 (estimated), works to renew the engine generator control system will be underway.

In the event of failure of the primary power source, Menorca Airport is unable to guarantee a maximum (light) switch-over time of 15 seconds in all lighting systems. This includes the approach systems of both thresholds, PAPIs, obstruction lighting, taxiway centre line lighting and apron lighting, which will remain inoperative for an estimated maximum of 15 minutes in the event of a failure of the primary power source. Should this inoperability occur, it will be announced via ATIS.

Critical lighting systems will not be affected. The maximum (light) switch-over time for these systems shall remain 1 second.

The effective start and end dates of the works will be announced via the corresponding NOTAM.

- SUP 27/25 -

