

ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA
Dirección AFTN: LEANZXTA
Teléfono: +34 913 213 363
E-mail: ais@enaire.es
Web: www.enaire.es

ENAIRE
DIVISIÓN DE INFORMACIÓN AERONÁUTICA
Avda. Aragón, 330. EDIFICIO 2
P.E. Las Mercedes - 28022 MADRID

SUP 142/20
03-DEC-20

AD

SUP 142/20 03DEC20/30SEP21EST
NOTA: SUP EST, sólo se cancelará por NOTAM, SUP o
enmienda al AIP.

MADRID/Adolfo Suárez Madrid-Barajas AD.- Balizamiento
de eje del giro entre TWY EB7-N10 fuera de servicio.

Hasta el 30 septiembre de 2021 estimado, el balizamiento de
eje del giro entre las TWY EB7-N10 permanecerá fuera de
servicio.

La puesta en servicio se publicará mediante NOTAM.

SUP 142/20 03DEC20/30SEP21EST
NOTE: EST SUP will only be cancelled by NOTAM, SUP or
AIP amendment.

MADRID/Adolfo Suárez Madrid-Barajas AD.- Centre line
lighting of the turn between TWY EB7-N10 out of service.

Until 30 September 2021 (estimated), the centre line lighting
of the turn between TWY EB7-N10 will remain out of service.

Its return to service will be published by NOTAM.

INTENCIONADAMENTE EN BLANCO
INTENTIONALLY BLANK