

# ESPAÑA

AIP-ESPAÑA

AIS-ESPAÑA  
Dirección AFTN: LEANZXTA  
Teléfono: +34 913 213 363  
E-mail: ais@enaire.es  
Web: www.enaire.es

ENAIRE  
DIVISIÓN DE INFORMACIÓN AERONÁUTICA  
Avda. Aragón, 330. EDIFICIO 2  
P.E. Las Mercedes - 28022 MADRID

SUP 170/21  
07-OCT-21

## AD

CANCELAR: SUP 142/20.

CANCEL: SUP 142/20.

SUP 170/21 07OCT21/07OCT22EST  
NOTA: SUP EST, sólo se cancelará por NOTAM, SUP o  
enmienda al AIP.

MADRID/Adolfo Suárez Madrid-Barajas AD (LEMD).-  
Balizamiento de eje del giro entre TWY EB7-N10 fuera de  
servicio.

Hasta el 07 de octubre de 2022 estimado, el balizamiento de  
eje del giro entre las TWY EB7-N10 permanecerá fuera de  
servicio.

La puesta en servicio se publicará mediante NOTAM.

SUP 170/21 07OCT21/07OCT22EST  
NOTE: EST SUP will only be cancelled by NOTAM, SUP or  
AIP amendment.

MADRID/Adolfo Suárez Madrid-Barajas AD (LEMD).-  
Centre line lighting of the turn between TWY EB7-N10 out  
of service.

Until 07 October 2022 (estimated), the centre line lighting of  
the turn between TWY EB7-N10 will remain out of service.

Its return to service will be published by NOTAM.

**INTENCIONADAMENTE EN BLANCO**  
**INTENTIONALLY BLANK**